

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back into different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR  
Tenneco Oil Company

3. ADDRESS OF OPERATOR  
P. O. Box 3249, Englewood, CO 80155

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1790' FNL 800' FWL "E"  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

(other) Commence drilling operations

SUBSEQUENT REPORT OF:

☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE  
SF-078201

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Florance

9. WELL NO.  
125

10. FIELD OR WILDCAT NAME  
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 1, T29N R9W

12. COUNTY OR PARISH 13. STATE  
San Juan New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6305' gr.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4/29/81 - MIRURT. Spud well 4/28/81 w/Four Corners rig #7. Drill to 276' POOH. RU and run 6 jts (264') 9-5/8" 36# csg set @ 276'. Cmt w/225 sx Class B w/2%  $CaCl_2$ . Plug down. Circ cmt to surface. WOC. Resume drilling.

5/2/81 - Drill 8-3/4" hole to 3525'. Circ and cond hole. TOOH. Laid down drill pipe and collars. RU and run 3531' of 7" 23# csg set @ 3525'. Cmt w/580 sx 65/35 POZ mix, tail in w/150 sx Class B w/2%  $CaCl_2$ . Plug down. Circ cmt to surface. WOC. NUBOE. Pressure test to 1000 PSI for 30 mins. OK. Resume drilling.

5/3/81 - Drill to TD on 5/6/81. POOH. Log w/Gearhart Owens. Laid down drill pipe. RU to run 4-1/2" liner.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles J. [Signature] TITLE Asst. Div. Adm. Mgr. DATE 5/13/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

\*See Instructions on Reverse Side