Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

Expires:	March :	31,	1993	

BUREAU OF L	5. Lease Designation and Serial No.	
	NM-012335	
SUNDRY NOTICES AN Do not use this form for proposals to drill	6. If Indian, Allottee or Tribe Name	
• •		
USE APPLICATION FOR	PERMIT - " for such proposals	7. If Unit or CA, Agreement Designation
SUBMIT	IN TRIPLICATE	
1. Type of Well		San Juan 30-5 Unit
Oil X Gas Other		8. Well Name and No.
2. Name of Operator		SJ 30-5 Unit #12
Phillips Petroleum Company		9. API Well No.
3. Address and Telephone No.	30-039-07721	
5525 Highway 64, NBU 3004, Farmingt 4. Location of Well (Footage, Sec., T., R., M., or Survey De		10. Field and Pool, or exploratory Area
Unit N, 990' FSL & 1650' FWL	•	Blanco Mesaverde
Section 31, T30N, R5W	11. County or Parish, State	
	Rio Arriba, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT	T, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans New Construction
X Subsequent Report	Recompletion	Non-Routine Fracturing
Subsequent report	Plugging Back	Water Shut-Off
Final Abandonment Notice	Casing Repair Altering Casing	Conversion to Injection
	X Other Add pay and stimulat	
	Callot Language Callot	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state algive subsurface locations and measured and true veri	pertinent details, and give pertinent dates, including estimated date of statical depths for all markers and zones pertinent to this work.)*	arting any proposed work. If well is directionally drilled
See attached for the procedure used	to add pay and stimulate the Lewis Shale	interval within the exiting
Mesaverde formation.		<u></u>
		• 3
14. I hereby certify that the foregoing is tribe and correct / Signed LUG!	Title Regulatory Assistant	
(This space for Federal or State office use)		
Approved by	Title	Date
Conditions of approval, if any:		
	on knowingly and willfully to make to any department or agency of the U	

* See Instruction on Reverse Side

1.1 1999



San Juan 30-5 #12 NM-012335; Unit N, 990' FSL & 1650' FWL Section 31, T30N, R5W; Rio Arriba County, NM

Details of procedure used to add and stimulate the Lewis Shale pay to the existing Mesaverde formation.

9/13/99

MIRU Key #29. Kill well w/2% KCl, ND WH & NU BOPs. PT - OK. COOH w/tbg. RIH w/bit & tagged fill @ 5897'. CO to PBTD @ 5922'. Circ. COOH. RIH w/5-1/2" CIBP & set @ 5300'. Load hole & PT plug, casing and rams to 550 for 30 minutes. Good test. COOH. RU Blue Jet & ran GR/CCL/CBL from 5295' to surface. Perf Lewis Shale @ 1 spf (.38") holes.

4726' - 4728' (3');	4671' - 4673' (3');	4660' - 4662' (3');	4618' - 4620' (3');
4596' - 4598' (3');	4580' - 4582' (3');	4409' - 4411' (3');	4358' - 4360' (3');
4347' - 4349' (3');	4340' - 4342' (3');	4331' - 4333' (3');	4304' - 4306' (3'); 36 holes

RIH w/FB packer & set @ 4133'. BJ & acidized perfs w/1000 gals 15% HCl & ballsealers. Unset packer & knocked balls off. Pulled up & set packer @ 5295'. PT CIBP to 3800 psi. OK. POOH w/packer. RU to frac. RIH w/5-1/2" FB packer & set @ 4139'. Pumped 70,173 gal of 60 Quality N2 foam consisting of 28,980 gal of 30# X-link gal & 880,000 scf N2 gas. Pumped a 4200 gal foam pad followed by 203,660 # of 20/40 Brady sand. Flushed w/35 bbls 2% KCl. ATR 35 bpm, ATP - 3650 psi, ISDP - 560 psi. Flowed back on 1/4" and 1/2" chokes for approx. 36 hrs.

RIH w/2-3/8" tubing and cleaned out fill to CIBP @ 5300'. Drilled out CIBP & circulated bottoms up @ 5314'. Cleaned out fill to PBTD @ 5918'. PU & set tubing @ 5816' with "F" nipple set @ 5785'. ND BOP & NU WH. PT - OK. Pumped off check. RD & released rig 9/19/99. Turned well over to production department.