| Form 3160-5<br>(November 1983)<br>(Formerly 9-331)                          | UNITED S   | TATES   | SUBMIT IN T<br>(Other !natruc<br>)R verse side)   | MORE OF TO  | Form approved. Budget Buresu No. 1004-0135 Expires August 31, 1985 5. LEADS DESIGNATION AND SERIAL NO.  |
|---|--|---|---|---|---|
| (Loumeirk A-221)  | BUREAU OF LAND   |   |   |   | SF-078741   |
| SUN<br>(Do not use thi  | NDRY NOTICES AND  Form for proposals to drill or  Um "APPLICATION FOR PE   | REPORTS O   | ck to a different res<br>possis   | ervole.   | 6. IF INDIAN, ALLOTTES OR TRISS NAME  |
| OIL GAS WELL  | Пх отвяв   |   | UJ120 -   | PM 3-51   | 7. CHIT AGREEMENT NAME San Juan 30-6 Unit   |
| 2. NAME OF OFERATOR   | El Paso Natura   | 1 Gas Compa   | A PARMINGTON.   | EN MEXICO   | San Juan 30-6 UnitNP  |
| 3. ADDRESS OF OPERATO   | / <b>-</b>   |   |   | 07400   | 9. WELL HO.   |
| 4. LOCATION OF WELL   | Post Office Bo   | cordance with any S   | DEFE  | <b>PVE</b> f  | 35<br>FIELD AND POOL, OR WILDCAT  |
| See also space 17 be<br>At surface  | 1060'N, 850'E  |   | M   |   | Blanco Mesa Verde   |
|   |  |   | FEB2 3  | 1989  | Sec. 24, T-30-N, R-6 -V   |
|   |  |   | OIL CON   | LDIV  | N.M.P.M.  |
| 14. PERMIT NO.  | 15. ELEVATION  | s (Show whether of,   | 95 'GL DIST.  |   | Rio Arriba NM   |
| 15.   | CL 1 A Pa  |   |   | 2   | <u> </u>  |
| <b>.</b> 0.   | Check Appropriate Bo   | i.<br>In stablent of Xi   | iture of inotice, f   | , •   | Her Udid  |
| TEST WATER SHCT-  | :  | CASING  | WATER SHUT-O  |   | REPAIRING WELL  |
| PRACTURE TREAT  | MULTIPLE COMP  |   | PRACTURE TRE  | i—  | ALTERING CLEING   |
| SHOOT OR ACIDIZE  | ABANDON*   | X   | SHOOTING OR   | CIDIZING  | ABANDONMENT <sup>®</sup>  |
| REPAIR WELL<br>(Other)  | CHANGE PLANS   | :   |   |   | f maitiple completion on Well   |
| FOR STRIBE PROPUSED (Proposed Work, nent to this work)                      | If west is directionally drilled, g  | ir state all perticent<br>ive supsurface location   | details, and give pe  | rtinent dates, in   | nciuding estimated date of starting any<br>depths for all markers and sones perti-  |
| MOL&RU well of Spot 3 perfs. w/2 7/ cover to cov retain from 2 (11.8 circla | l. Blow well dow<br>lean w/9 ppg, 50<br>0 sx plug (35.4<br>WOC. TIH, tag p<br>'8". TIH, CO, spo<br>Pictured Cliffs.<br>er Kirtland and<br>her @ 2380'. Sti | on, test BO sec/qt. m cu.ft.) frolug, freepot 30 sx pl Spot 85 Fruitland. ng into refer Ojo Ala of retainer i.2 cu.ft.) ng and inst | P. PU 1 1/ ud (15 1bs om 5645-50 oint 2 7/8 ug (35.4 c sk plug (1 TOOH. Pe tainer, sq mo. Pull o TOOH. from surf all dry ho | 2" works /bbl sol 75', to ", cut 2 u.ft.) f 00.3 cu. rf 4 hol ueeze 35 ut of re Shoot 4 ace up t le marke | dium bentonite).  cover Mesa Verde and  7/8" @ 3540'. TOOH  rom 3540-3432' to  ft.) from 2892-2450' es @ 2450', set cmt.  sx (41.3 cu.ft.)  tainer, spot 10 sx  holes @ 300',  hrough 10 3/4" |
| 18. I hereoy certify, the   | at the foregoing is true and cort  | MOHING MOC  | S OF APPROV   |   |   |
| SIGNED SOM  | my Stalful   | TITLE Re  | gulatory A  | rrairs (  | WS) DATE  |
| (This space for Fe  | deral or State office use)   |   |   |   | A   |
| APPROVED BY _<br>CONDITIONS OF  | APPROVAL, UF ANT:  | TITLE   |   |   | 17 17 1999  |
|   |  |   |   | /   | Shelle .  |
|   | , k  | *See Instructions   | on Reverse Side   | ton   | REA MANAGER   |

## BUREAU OF LAND MANAGEMENT 1235 La Plata Highway Farmington, New Mexico 87401 Phone (505) 327-5344

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 35 San Juan 30-6 Unit

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 327-5344.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable): Add a plug from 3200'-3100' Protured Cliffs

Bring Surface plug down to 344-surface (Surface casing Shoe @ 294')

Office Hours: 7:45 a.m. to 4:30 p.m.

## GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6%/gal slurry weight is to be used when using class B neat cement or when CaCl<sub>2</sub> is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).

から、このは、日本のでは、このでは、一人のでは、一人のでは、日本にのでは、日本ので

- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
  - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

  Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

Company of the Compan

- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

ේ ල්ලිකාවය. මහත් දැපුරුවල් සිතුරිකානය ලේ. විතා කරන්න පළමුවල් මිනි දැක්වීමට ප්රධාන කරන දිය දැක්වීම් දියිම් වර්ති වර්තනකාන මිනිසු වේ.මිනිත්ත කුණුම්තු දෙනකානේ දිනිත්ත වර්ත මෙම නියලිකාවට දිය ද අදුල් විදිහිට වැනි දැක්වීමට දැක්වීම් වන දිනිකුත්තේ තුරුවේ දිනිත අතර විතාකක්ෂණ පොලා අවස්