

36 MAR 22 AM 3:10

RECEIVED
MAR 28 1996

MERIDIAN OIL OIL CON. DIV.
DIST. 3

PO Box 4289, Farmington, NM 87499 (505) 326-9700

5. Lease Number
SF-079074

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

San Juan 30-6 Unit

8. Well Name & Number
San Juan 30-6 U #72

9. API Well No.
30-039-07818

10. Field and Pool
Blanco Mesaverde

11. County and State
Rio Arriba Co, NM

Type of Action

<u> </u>	Notice of Intent	<u> X </u>	Abandonment	<u> </u>	Change of Plans
<u> X </u>	Subsequent Report	<u> </u>	Recompletion	<u> </u>	New Construction
<u> </u>	Final Abandonment	<u> </u>	Plugging Back	<u> </u>	Non-Routine Fracturing
		<u> </u>	Casing Repair	<u> </u>	Water Shut off
		<u> </u>	Altering Casing	<u> </u>	Conversion to Injection
		<u> </u>	Other -		

2-28-96 MIRU. SDON.
2-29-96 ND WH. NU BOP. TOO H w/184 jts 2 3/8" tbq. TIH w/4 1/2" gauge ring to 4980'.
TOOH. TIH w/4 1/2" CIBP, set @ 4980'. TOO H. TIH. SDON.
3-1-96 Tag up on 4 1/2" CIBP @ 4980'. Load csg w/wtr. PT csg to 500 psi, failed.
Circ hole w/25 bbl wtr. Plug #1: pump 12 sx Class "B" cmt inside csg on
top of CIBP @ 4820-4980'. TOO H. TIH, perf 3 sqz holes @ 3257'. Establish
circ out csg annulus w/40 bbl wtr. Circ hole clean. SD for weekend.
3-4-96 Establish circ out 7 5/8" csg w/40 bbl wtr. ND BOP. Weld on 4 1/2" collar on
csg stub. TIH w/chemical cutter, cut 4 1/2" csg off @ 3213'. Circ hole
clean. TOO H w/30 jts 4 1/2" csg. SDON.
3-5-96 Circ hole clean. TOO H w/71 more jts 4 1/2" csg. PT csg to 500 psi, failed.
TIH, perf 3 sqz holes @ 3212'. TOO H. TIH w/cmt retainer, set @ 3178'.
Attempt to establish injection, failed. (Verbal approval to change plans
from Ken Townsend, BLM). Plug #2: pump 39 sx Class "B" cmt inside 7 5/8"
csg @ 3004-3178'. TOO H to 2990'. Reverse circ tbq clean w/15 bbl wtr.
Reverse circ 0.25 bbl cmt to surface. TOO H. TIH, perf 3 sqz holes @ 2972'.
TIH w/cmt retainer. Cannot get past tbq head. SDON.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed Wesley D. Adams Title Regulatory Administrator Date 3/20/96

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

MAR 26 1985
Sharon Spurr
 DISTRICT MANAGER

NMOC

3-6-96 Well SI WO equipment.
3-7-96 TIH w/7 5/8" cmt retainer, set @ 2926'. Establish injection. Plug #3: pump 23 sx Class "B" cmt below cmt retainer into sqz holes @ 2972' & outside 7 5/8" csg. Pump 27 sx Class "B" cmt inside csg @ 2814-2926'. TOOH to 2424'. Plug #4: pump 140 sx Class "B" cmt inside 7 5/8" csg @ 1800-2420'. TOOH to 1609'. Plug #5: pump 38 sx Class "B" cmt outside csg. Circ w/8 bbl wtr. Displace cmt to 1969', left 102 sx cmt inside csg. WOC. PT csg to 500 psi, failed. TOOH. TIH, tag TOC @ 2210'. Plug #6: pump 56 sx Class "B" cmt @ 1959-2209'. TOOH to 1019'. WOC. SDON.
3-8-96 TIH, tag TOC @ 1492'. TOOH to 1347'. Plug #7: pump 38 sx Class "B" cmt @ 1175-1347'. TOOH to 250'. Establish circ out bradenhead. Plug #8: pump 65 sx Class "B" cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. ND BOP. Did not cut off WH. Install dry hole marker w/88 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 3-8-96.