

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. New Mexico 013706-A
2. NAME OF OPERATOR Blackwood & Nichols Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1237, Durango, Colorado 81301		7. UNIT AGREEMENT NAME Northeast Blanco Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 420' F/SL - 2515' F/EL		8. FARM OR LEASE NAME Northeast Blanco Unit
14. PERMIT NO.	15. ELEVATIONS (Show whether to top of rock)	9. WELL NO.
	6282' GL	10. FIELD AND ZONE Blanco Mesaverde
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17 30N-7W NMPM
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pull 2-3/8" tubing, set bridge plug at 4925' in 5-1/2" casing; test 5-1/2" casing for leaks, repair if necessary; recover plug, clean out to 5560'. Run 4" flush joint liner and cement; perforate the Mesaverde Zone and sand-water fracture in two stages; rerun 2-3/8" tubing and return well to production.



JAN 21 1976

18. I hereby certify that the foregoing is true and correct

SIGNED DeLasso Loos TITLE District Manager

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 1-20-76

DATE _____

*See Instructions on Reverse Side

SA.