UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	
5.	Lease Number NM-0338# 5
1. Type of Well GAS	If Indian, All. or Tribe Name
7.	Unit Agreement Name San Juan 30-6 Unit
2. Name of Operator BURLINGTON BESOITECES	San Juan 30-6 Jine
RESOURCES OIL & GAS COMPANY 8.	Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-3766 9.	San Juan 30-6 Unit #17 API Well No. 30-039-07833
4. Location of Well, Footage, Sec., T, R, M 800'FSL, 1500'FWL, Sec.18, T-30-N, R-6-W, NMPM	. Field and Pool Blanco Mesaverde
\sim	County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER Type of Submission Type of Action X Notice of Intent Abandonment Change of P. Recompletion New Construction Subsequent Report Plugging Back Non-Routine Casing Repair Water Shute Altering Casing Conversion X Other - Spinner Survey 13. Describe Proposed or Completed Operations It is intended to run a spinner survey in the subject well acceptocedure and wellbore diagram.	lans ction Fracturing off to Injection ording to the attached
14. I hereby certify that the foregoing is true and correct. Signed Machine Title Regulatory Administrator Da	ECEIVED BLM -2 1M 9: 04 ate 6/30/99
(This space for Federal or State Office use) APPROVED BY Spencer Title CONDITION OF APPROVAL, if any:	JUL 20 100.

San Juan 30-6 Unit #17

Unit N, Section 18, T30N, R06W Rio Arriba County, New Mexico Elevation 6630' GL, 6640' KB

LAT: 36° 48.4442' Long: 107° 30.4459'

Summary:

The San Juan 30-6 Unit #17 was spudded in August of 1957 and was originally completed in the Point Lookout and Cliff House. In November of 1991, the Lewis was completed in one stage. A spinner survey with data from other spinner surveys and the Shale Data Wells, will also be used in the completion design optimization of the Lewis.

Procedure:

1. Comply with all NMOCD, BLM, and BR regulations. Conduct daily safety meetings for all personnel on location.

DO NOT KILL WELL. ANY FLUIDS USED IN WELLBORE WILL INVALIDATE DATA. IF FLUIDS ARE REQUIRED, CONTACT MICHELE QUISEL TO DISCUSS ALTERNATIVES.

- 2. Inspect location and wellhead and install rig anchors prior to rig move if needed.
- 3. RU slickline unit. RIH w/ slickline and set tubing choke in FN @ 5944'. RD slickline unit.
- 4. MIRU. Check all safety equipment to insure proper location and working order. ND wellhead and NU BOP, spool, stripping head and blooie line to pit. Continue to flow well through casing valve. Flow well through casing valve and blow well through blooie line to pit.
- 5. Strip 192 jts. 2-3/8" 4.7# J-55 tubing through stripping head and stand back. SI rams on BOP. ND stripping head. Place well back on production down the line.

THE WELL WILL REMAIN ON PRODUCTION DURING THE ENTIRE SPINNER SURVEY.

- 6. RU Schlumberger and full lubricator. Open rams on BOP and RIH w/ spinner flowmeter tool/GR/CCL/Gradio. Correlate depth to GR/CCL logs provided by the engineer on location.
- 7. Take spinner survey readings at the following stations:

Station #1
 4580' Top of Navajo City Chacra

Station #2
Station #3
4625' Top of Otero Chacra
4730' Top of Middle Bound

Station #3
Station #4
4730' Top of Middle Bench
5000' Top of Massive Cliff House

- 8. Tag bottom w/ spinner tool. POOH w/ spinner flowmeter tool/GR/CCL/Gradio and SI rams on BOP. RD and release Schlumberger.
- 9A. If fill, TIH w/ 4-3/4" bit and CO to PBTD. TOOH.

San Juan 30-6 Unit #17

Unit N, Section 18, T30N, R06W Rio Arriba County, New Mexico Elevation 6630' GL, 6640' KB

LAT: 36° 48.4442' Long: 107° 30.4459'

9. NU stripping head. Open rams on BOP. Strip 192 jts. 2-3/8" 4.7# J-55 tubing w/ expendable check and seating nipple one joint off bottom and land tubing @ 5944'. ND stripping head, BOP, spool, and blooie line. NU wellhead. Pump off expendable check. Place well on production. RD and release rig.

Recommend:

Approve: Zruce (). Bong. 6.78.99
Drilling Superintendent

Vendors:

Wireline: Schlumberger

328-5006

Michele Quisel Steve Campbell Hans Dube

Pager: 326-8196 Pager: 564-1902

Home: 564-9097 Home: 325-8218

Office: 326-9546 Office: 326-9555 Glen Christiansen

Home: 564-9401

Office: 326-9733

Office: 324-6162

Home: 327-5089

San Juan 30-6 #17

800 FSL, 1500 FWL Unit N Sec. 18, T-30 R-06W Rio Arriba County, New Mexico

KB 6640

GL 6630

LAT: 36 48.4442, LONG: 107 30.4459

