

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-347-17

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name San Juan 30-6 Unit
1. Name of Operator Meridian Oil Inc.	8. Farm or Lease Name San Juan 30-6 Unit
2. Address of Operator P.O. Box 4289, Farmington, New Mexico 87499	9. Well No. 85
3. Location of Well UNIT LETTER <u>L</u> <u>1647</u> FEET FROM THE <u>South</u> LINE AND <u>900</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>30N</u> RANGE <u>06W</u> NMPM.	10. Field and Pool, or Wildcat Blanco Mesaverde
15. Elevation (Show whether DF, RT, GR, etc.) 6567' GL	12. County Rio Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Emergency Casing Repair	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to repair casing in the following manner:

Move on location, rig up. Pull 2 3/8" tubing. Chemically cut 4 1/2" casing @ + or- 5000' & pull out of hole. Squeeze cement 7" casing with sufficient cement. Re-run 4 1/2" casing, tie-back with casing patch. Cement 4 1/2" casing. Clean out to PBTD. Re-run 2 3/8" tubing. Return well to production.

RECEIVED
OCT 27 1989
OIL CON. DIV.
DIST. 3

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Regulatory Affairs DATE October 25, 1989

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT 3 DATE OCT 27 1989

CONDITIONS OF APPROVAL, IF ANY:

Notify this office 24 hrs. before work can't get

San Juan 30-6 Unit # 85
SW/4 Section 16, T-30-N, R-6-W
Rio Arriba County, New Mexico

Wellbore Schematic

C U R R E N T

