

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-039-07859
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-347

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG EXISTING DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Lease Name or Unit Agreement Name: San Juan 30-5 Unit
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	8. Well No. SJ 30-5 Unit #13	
2. Name of Operator Phillips Petroleum Company	9. Pool name or Wildcat	
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401		
4. Well Location Unit Letter <u>B</u> : <u>990'</u> feet from the <u>North</u> line and <u>1650'</u> feet from the <u>East</u> line Section <u>16</u> Township <u>30N</u> Range <u>5W</u> NMPM County <u>Rio Arriba</u>	10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6358.6'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: Squeeze, perf and stimulate Lewis Shale <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

MIRU. ND WH & NU BOP. POOH w/production tubing. Isolate existing Mesaverde perfs with bridge plug. PT casing. If casing fails test - isolate failure and remediate with cement.

Our well records indicate not enough cement set across the Lewis Shale interval and it will be necessary to shoot squeeze holes in the casing and will have to pump sufficient volumes of cement to cover and isolate the Lewis Shale.

Perforate and stimulate the Lewis Shale (perfs to be determined aafter logs are run). Retrieve bridge plug and run production tubing. Flow test the Lewis Shale. A workover pit will be required.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE Patsy Clugston DATE 9/26/00
Type or print name Patsy Clugston Telephone No. 505-599-3454

(This space for State Official Signed by CHARLIE T. PERREN)

DEPUTY OIL & GAS INSPECTOR. DIST. SEP 27 2000

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: