Form 3160-5 (November 1983) (Formerly 9-331)	UNITED DEPARTMENT OF		SUBMIT IN TRIPLICATE Other instructions of r	Expires rugust	31, 1985	
(1.01me113 3=221)	BUREAU OF LAN		( verse alde)	5. LEASE DESIGNATION	AND SERIAL NO.	
CLIA		SF-079484-A	SF-079484-A  6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
Oo not use this	IDRY NOTICES AN form for proposals to drill o Use "APPLICATION FOR P	THE REPORTS ON The to deepen or plug back ERMIT—" for such propose	WELLS to a different reservoir. als.)		THE NEXT	
OIL GAS G				7. UNIT AGREEMENT NA	7. UNIT AGREEMENT NAME	
WELL WELL X OTHER  2. NAME OF OPERATOR				San Juan 30-4 Unit		
				8. FARM OR LEASE NAM	_	
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR				San Juan 30	San Juan 30-4 Unit	
P.O	. Box 4289, Farmin	gton, New Mexic	o 87499	16		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  P.O. BOX 4289, Farmington, New Mexico 87499  E. C. E. I. V.					10. FIELD AND POOL, OR WILDCAT	
890'S G 890'W				East Blanco Pictured Cliffs 11. SEC., T., E., M., OR BLK. AND Ext		
MAY 01 1985				SURVEY OR AREA EXT.		
		EUREAU OF LAN	D MANAGEMEL .	Section 10. T30	N RAW	
14. PERMIT NO.		ons (Show whether br, RT, i	ik, etc. POF APE	Section 10, T30	13. STATE	
	737	4' GL		Rio Arriba	New Mexico	
16.	Check Appropriate B	lox To Indicate Natur	e of Notice, Report, or	Other Data		
1	NOTICE OF INTENTION TO:			QUENT REPORT OF:		
TEST WATER SHUT-O	PULL OR ALTER	CASING	WATER SHUT-OFF	BEPAIRING W	ELL	
FRACTURE TREAT	MULTIPLE COM	PLETE	FRACTURE TREATMENT	ALTERING CA	BING	
SHOOT OR ACIDIZE REPAIR WELL	ABANDON*	X	SHOOTING OR ACIDIZING	ABANDONMEN	r*	
(Other)				s of multiple completion of	n Well	
17. DESCRIBE PROPOSED OF proposed work. If	COMPLETED OPERATIONS (Clear well is directionally drilled,	rly state all pertinent det give subsurface locations	Completion of Recolar	DIETION REPORT and I on for	- \	
	A subject well und				and south perti-	
			- <del>-</del>			
displace w/16 plug to cover casing @ 182'	e w/water. Spot 2 bbls. 9#/gal gel. Fruitland, Kirtla w/2 shots. Pump Cut off both casin	Pull out 7 jt nd & Ojo Alamo. 63 sx cement to	s. of tubing to 39 Flush tubing wi cover 50' below	945'. Spot 50 s th 15 bbls. gel. casing shoe and	x cement Perf circulate	
	•			»·	į.	
				*	-	
			[AD	PROVED		
18. I hereby certify that	the foregoing is true and corn		ction Engineer	DATE April	30, 1985	
(This space for Feder	al or State office use)			0.1.1005		
APPROVED BY		TITLE		MAY U1 1985		
CONDITIONS OF AP	PROVAL, IF ANY:		tor FARMI	AREA MANAGER NGTON RESOURCE AREA		
T:u_ 10 H C C C	1001	*See Instructions on I			-i	