Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: Merch 31 1993

Expires:	March	31,	1993	
 				۰

5.	Lease	Designation	and	Serial	No

NM-03404

SUNDRY	NOTICES AND	REPORTS ON	WELLS	
Do not use this form for pro	posals to drill or	to deepen or re	eentry to a differen	And semobile !!
LL #ADDI	IOATION FOR B	FDMT " 4		STORES IN IT

•	If	Indian,	Allottee	or	Tribe	Name	

Use "APPLICATION FOR	PFRMIT - " for such	proposale / L	- (m)	27 11	U L			
SUBMIT	IN TRIPLICATE	M	LOCT	2 1	1999	If Unit or	CA, Agreement	Designation
I. Type of Well Oil X Gas Well Other						San Juan 8. Well Nam	31-6 Unit e and No.	
2. Name of Operator Phillips Petroleum Company	·	·	(D)	il.Vo	5	SJ 31-6 Unit #14 9. API Well No.		
3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farmingt		505-599-	3454			30-039-07907 10. Field and Pool, or exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit M, 1135' FSL & 1090' FWL Section 5, T30N, R6W						or Parish, State		
CHECK APPROPRIATE BOX(s) TO INDICATE NA	ATURE OF N	OTICE	, REP	ORT, (Rio Arrit OR OTHER		NM
TYPE OF SUBMISSION			TYPE	OF AC	TION			
Notice of Intent	- Fi	bandonment ecompletion					e of Plans	
Subsequent Report		lugging Back					Routine Fracturin	og
Final Abandonment Notice	A	Itering Casing	y and	stimu	ılate	_ Dispo	ersion to Injectionse Water	
. Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vert	pertinent details, and give pe	rtinent dates, includ I zones pertinent to	ling estima	ated date	of startin	Completion	or Recompletion Re	port and Log form.)

See the attached for the procedure used to add pay and stimulate the Lewis Shale interval within the existing Mesaverde formation.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

1999

Simm.



San Juan 31-6 #14 NM-030404; Unit M, 1135' FSL & 1090' FWL Section 5, T30N, R6W; Rio Arriba County, NM

Procedure used to add pay and stimulate the Lewis Shale interval within the existing Mesaverde formation.

10/5/99

MIRU Key Energy #18. Kill well w/KCL water. ND WH & NU BOPs. PT - OK. Pulled tubing hanger & GIH & tagged & cleaned out fill to PBTD @ 5624'. COOH w/2-3/8" tubing. Made 4-3/4" bit & 5-1/2" scraper run to 5200'. COOH. RIH w/5-1/2" CIBP & set @ 5150'. Load hole & PT Casing, CIPB to 500 psi for 30 minutes - OK. COOH. RU Blue Jet & ran GR/CCL/CBL from 5154 to 3354' (liner top). TOC @ 2770'. Perforated Lewis Shale interval @ 1 spf - .38" holes as follows:

4558' - 4560' (3');	4525' - 4527' (3');	4475' - 4477' (3');	4405' - 4407' (3');
4389' - 4391' (3');	4337' - 4339' (3');	4228' - 4230' (3');	4128' - 4130' (3');
4117' - 4119' (3');	4084' - 4086' (3');	4052' - 4054' (3');	4004' - 4006' (3'); 36 holes total

RIH w/FB packer & set @ 3788'. RU to acidize. Pumped 1000 gal 15 % HCL w/ballsealers. Knocked balls off. COOH w/packer. RIH w/5-1/2" FB pecker & set @ 3387'. PT - OK. RU to frac. Pumped 65,000 gal of 60 Quality 30# X-link Borate gel N2 foam w/200,000 # 20/40 Brady sand. ATP - 2700 psi, ATR - 45 bpm, ISIP - 650 psi. Flowed back on 1/4" and 1/2" chokes for approx. 40 hours. Released packer & COOH. RIH w/2-3/8" tubing and cleaned out fill, then PUH & set tubing @ 4541' with "F" nipple set @ 4508'. ND BOP & NU WH. PT - OK. Pumped off expendable check. RD & released rig 1830 hrs 10/12/99. Turned well over to production department.