

Form 5-331  
(May 1963)

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <b>Contract 465</b>	
2. NAME OF OPERATOR <b>Dugan Production Corp.</b>		6. IF INDIAN, ALIOTTEE OR TRIBE NAME <b>Jicarilla</b>	
3. ADDRESS OF OPERATOR <b>Box 234, Farmington, New Mexico 87401</b>		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>330' FNL - 330' FEL</b>		8. FARM OR LEASE NAME <b>La Corina</b>	
14. PERMIT NO.		9. WELL NO. <b>35</b>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>7795' GR - 7807' RKB</b>		10. FIELD AND POOL, OR WILDCAT <b>Wildcat</b>	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 6, T30N, R1E</b>	
		12. COUNTY OR PARISH <b>Rio Arriba</b>	13. STATE <b>NM</b>

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well will be abandoned in the following manner:

1. Spot 100' cement plug across top of Hermosa 4300-4200'
2. Spot 100' cement plug across top of Entrada 3450-3350'
3. Spot 100' cement plug across top of Dakota 2350-2250'
4. Spot 100' cement plug at base of surface pipe 250-150'
5. Spot 10 sx in top of surface pipe
6. Erect dry hole marker and abandon well.

VERBAL APPROVAL RECEIVED FROM JERRY W. LONG, DISTRICT ENGINEER, 7-3-74.



18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by  
Jim L. Jacobs TITLE Geologist DATE 7-10-74  
Jim L. Jacobs

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side