14. PERMIT NO.

UNITED STATES

SUBMIT IN TRIPLICATES (Other Instructions on re-

		Form a Budget	pprov Bure	rd. L	и о. 41	2 R	142
	LEASE	DESIGN	ATTON	·γKb	SER	EAT,	ĸo.
_		illa					
3	0-03	9-21	036				

12. COUNTY OR TARISH 13. STATE

Rio Arriba

New Mexico

DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL EO. Jicarilla 511 30-039-21036	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	Jicarilla	
OIL XX GAS OTHER	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR	8. FARM OR LEASE NAME	
Union Oil Company of California	Jicarilla	
3. ADDRESS OF OPERATOR	9. WELL NO.	
P. O. Box 2620 - Casper, Wyoming 82601	1 (N31)	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface	Wildcat	
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
577' FSL & 2303' FWL		
	Sec. 31, T.30N.,R.1W.	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

7442' G.L.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
				· · · · · · · · · · · · · · · · · · ·			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL		CHANGE PLANS		(Other) Supplementary V			
(Other)				(Note: Report results of m Completion or Recompletion	altiple completion on Well Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

7030' T.D.

SICP (154 Hrs) 20#. Ran 5-day BHP bomb 5-22-75. P.O.O.H. with BHP bomb. Pressure at bomb 2180#, at surface 20#. 30-Hr. bomb 2118#, at surface zero. 60-Hr. bomb 2112#. 90-Hr. bomb 2104#. 116-Hr. bomb 2098#. Re-ran 5-day BHP bomb.

P.O.O.H. with BHP bomb. Bomb at 5888'. Press. 5 days, 2142#.

MIRU pulling unit. Ran and landed tubing at 6,591.54. Ran rods and pump and placed Have recovered 1269 bbls. of 3080 bbl. load oil. well on production. Pump testing.



3.	I hereby certify that the foregoing is true and correct SIGNED	TITLE District Drilling Supt.	DATE 6-30-75
	(This space for Federal or State office use)		
	APPROVED BY	TITLE	DATE