

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-039-21276
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name 009258
San Juan 30-5 Unit
8. Well No. SJ 30-5 Unit #57
9. Pool name or Wildcat 72319 Blanco Mesaverde

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER
2. Name of Operator Phillips Petroleum Company 017654
3. Address of Operator 5525 Hwy. 64, NBU 3004, Farmington, NM 87401
4. Well Location Unit Letter <u>A</u> : <u>1190</u> Feet From The <u>North</u> Line and <u>1040</u> Feet From The <u>East</u> Line Section <u>28</u> Township <u>30N</u> Range <u>5W</u> NMPM <u>Rio Arriba</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>Perforate & produce Lewis Shale</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set retrievable bridge plug above current Mesaverde perms. Pressure test RBP & casing. Run GR/CCL & CNL if needed. Perforate the Lewis Shale formation @ 1 spf w/120 degree phasing. Frac the Lewis Shale. Retrieve bridge plug. RIH w/2-3/8" production tubing w/gas lift mandrel and blast joints across Lewis perms, 4-1/2" production packer and "R" profile nipple above the bottom joint of tubing and an expendable check valve on the end of the tubing. Using a slick line, remove blanking plug. Produce Lewis for a period of time to record daily volumes and pressures and then produce both zones.

RECEIVED
MAR - 6 1996

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ed Hasely TITLE Environmental/Regulatory DATE 3-4-96
TYPE OR PRINT NAME Ed Hasely TELEPHONE NO. 505-599-3454

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #2 DATE MAR - 6 1996
CONDITIONS OF APPROVAL, IF ANY: