UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 012331 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1100' FNL & 1640' FEL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	7. UNIT AGREEMENT NAME San Juan 30-5 Unit 8. FARM OR LEASE NAME San Juan 30-5 Unit 9. WELL NO. 59 10. FIELD OR WILDCAT NAME Blanco Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC 31, T30N, R5W 12. COUNTY OR PARISH 13. STATE Rio Arriba N.M.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Set cmt_ret	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6830' GR		

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - 1. Run gauge ring to find top of RTTS.
 - 2. Set cmt ret between RTTS & perf @ 3712'.

Subsurface Safety Valve: Manu. and Ty	/pe	Set @ /	Ft.
18. I hereby centify that the foregoing	is true and correct		
SIGNED P.M. Pippin	is true and correct TITLE Production EngineerATE	6/22/78	
	(This space for Federal or State office use)	- 	
APPROVED BY	TITLE DATE _		