UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Noti	ces and Reports on Wells		
		5.	Lease Number SF-079485A
1. Type of Well GAS	2 8 10gz	6.	If Indian, All. or Tribe Name
2. Name of Operator	OUL COM.	7.	Unit Agreement Name San Juan 30-4 Unit
MERIDIAN OIL		8.	Well Name & Number
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM		9.	San Juan 30-4 U #39 API Well No. 30-039-22210
4. Location of Well, Footage, Sec., T, R, M 1520'FNL, 720'FWL Sec.18, T-30-N, R-4-W, NMPM			Field and Pool Basin Dakota County and State
		11.	Rio Arriba Co, NM
to produce against currently at 380 p this well economic	Plugging Back Non-R Casing Repair Water Altering Casing Conve X Other - Long term shut-in	Shut o rsion t is well ine preseing evaris being	Fracturing ff o Injection will be unable ssure is aluated to make addressed.
currently show a chazards.	casing leak so there should be n	no envi:	ronmental
	AL EXPIRES AUG 01 1995		RECEIVED BLM 3: 57
14. I hereby certify that the Signed May Machille	foregoing is true and correct. Title Regulatory Affairs		7/20/94
(This space for Federal or Stat	e Office use) Title	Date _	
CONDITION OF APPROVAL, if any:			PROVED
			. 11 42 4 50