

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Southland Royalty Company		8. Farm or Lease Name Simms Federal	
3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87401		9. Well No. 1	
4. Location of Well UNIT LETTER <u>J</u> , <u>1730</u> FEET FROM THE <u>South</u> LINE AND <u>1820</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>30 North</u> RANGE <u>4 West</u> NMPM.		10. Field and Pool, or Wildcat East Blanco PC/ Basin Dakota	
15. Elevation (Show whether DF, RT, GR, etc.) 7023' GL		12. County Rio Arriba	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon Lower Dakota perforations (8670'-8684') by setting CIBP at 8650'. Plan to perforate, acidize and swab test from 8633'-8636'. If this zone is non-commercial will plug and abandon by spotting cement plug from CIBP to 8580'.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F. E. Fidler TITLE District Engineer DATE August 24, 1981

APPROVED BY Original Signed by FRANK T. CHAVEZ

TITLE SUPERVISOR DISTRICT # 3

DATE AUG 27 1981

CONDITIONS OF APPROVAL, IF ANY: