## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	Budget Bureau No. 42-R1424
	5. LEASE NM 012735
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
nt	7. UNIT AGREEMENT NAME San Juan 31-6 Unit
	8. FARM OR LEASE NAME San Juan 31-6 Unit
	9. WELL NO. #3A
	10. FIELD OR WILDCAT NAME Blanco Mesa Verde
17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 6, T30N, R6W
	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 87401
	14. API NO

30-039-22757 15. ELEVATIONS (SHOW DF, KDB, AND WD)

6280 GR

OTE: Report re

\_\_\_ DATE \_\_

(Do not use this form for proposals to drill or to deepen or plug back to a difference reservoir. Use Form 9-331-C for such proposals.) gas 1. oil Ď well

other

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

Northwest Pipeline Corporation

AT SURFACE: 745 FSL & 1995 FEL AT TOP PROD. INTERVAL: Same as above

AT TOTAL DEPTH: Same as above

P.O. Box 90, Farmington, N.M. 87401

well

2. NAME OF OPERATOR

below.)

REPAIR WELL

3. ADDRESS OF OPERATOR

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

SUNDRY NOTICES AND REPORTS ON WELLS

REPAIR WELL	; H1	chan	re on Form 9-330.)	1
PULL OR ALTER CASING L MULTIPLE COMPLETE		GEOLOGICAL SURVEY.	OCT 3 0 1981	
CHANGE ZONES		FARMINGTON, N. M.	1 201 30 1301	1
ABANDON*	j 🔲 🗀 🗀		OIL CON. COM.	
(other)			DIST. 3	<u>/</u>
measured and true vertica 10-16-81 & 10-17-8 float collar @ 568 hole & spotted 750 30 holes from 5130 dropped 50 balls, rec'ed 50 balls w, by 100,000# 20/40 BPM; MIR 60 BPM; A 10-17-81. Cleaning 10-18-81 Cleaning 10-19-81 Ran 177 5464' KB. Seating tbg. Well SI and IP TEST. Subsurface Safety Valve: Manual	of starting any proposed work I depths for all markers and 20 31 MOL & RU. PU 3-84' KB. Pressure test of gal of 7-1/2% HCl of to 5607'. Smith for sand @ 1-2 ppg. To ATP 1700#, MTP 1800# and well after from the sand @ 1-2 ppg. To ATP 1700#, MTP 1800# and the sand well after from the sand well after from the sand of th	nes pertinent to this work.)  7/8" bit on 2-3/8"  sted csg to 3200# facross perfs. Blue broke down MV w/ 10  t did not ball off. aced w/ 10,000 gal  tal fluid to recove , ISIP 0#. Job cor ac.  c.  8", 4.7#, J-55 EUE tm jt. Pumped out uction Department.	tbg & cleaned out for 15 min - OK. C Jet ran GR/CC1 & OOO gal 7-1/2% HC1 Ran junk basket pad treated wtr fo er 1735 bbls. AIR mpleted @ O315 hrs  , 9RD, tbg & landed plug & gauged well WAITING ON CLEAN	to irc perfec & & 1lowed 59
SIGNED Doma A.	Brace TITLE Prod	uction Clerk DATE _	10-26-81	

SUBSEQUENT REPORT OF

APPROVED BY

Donna J. Brace

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

(This space for Federal or State office use)

EST