Submit 3 Copies To Appropriate District State of N	ew Mexico	Form C-103
Office Energy, Minerals and	l Natural Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240	ATION DIVICION	30-039-22786
811 South First, Artesia, NM 87210 2040 Sou	th Packago	5. Indicate Type of Lease
	NM 57505	STATE FEE X
District IV 2040 South Pacheco, Santa Fe, NM 87505	NOV 2001	State Oil & Gas Lease No.
THE PROPERTY OF THE PERSON OF	N WELLS	7: Lease Name or Unit Agreement Name:
LIBO NOT LIGHTING FORM FOR PROPOSALS TO DRILL OK 10 DB		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOI PROPOSALS.)	RM (देशका) FOR accent =	Bixler Ranch
1. Type of Well:		
Oil Well Gas Well X Other		8. Well No.
2. Name of Operator		1
ENERGEN RESOURCES CORPORATION 3. Address of Operator		9. Pool name or Wildcat
2198 Bloomfield Highway, Farmington, NM 87401		East Blanco PC
4. Well Location		
Unit Letter E : 1790 feet from the	North line and	990 feet from the West line
m 1.	30N Range 4W	NMPM County Rio Arriba
Section 26 Township 10. Elevation (Show)	whether DR, RKB, RT, GR, e	etc.)
7277 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
	ndicate Nature of Notice	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO:		
PERFORM REMEDIAL WORK PLUG AND ABANDO		
TEMPORARILY ABANDON	COMMENCE DRIL	ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST ANI CEMENT JOB)
OTHER: Repair casing Leak	X OTHER:	
To Describe the Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompilation.		
During the course of unplugging tubing in this well, it was discovered it had a casing leak. It is		
intended to repair the leak as follows:		
1. TIH with packer and RBP. Set RBP at 3900'. Test plug and isolate casing leak.		
2. Squeeze cement leak with sufficient amount of cement to circulate to surface if returns are		
established. WOC		
3. TIH and drill out squeeze. Test casing to 500 psi.		
 TIH and retrieve RBP. TOH TIH and clean out with air mist. Land tubing at 4200'. Return to production. 		
5. Till and Group care		
		_
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
I hereby certify that the information above is true and complete to m		
SIGNATURE 110kg Whater	TITLE Production As	sistant DATE 11/8/01
Type or print name Vicki Donaghey		Telephone No. 505-325-6800
(This space for State use)	DEPOTY OF 2 6	AS INSPECTOR PIST # NOV - 9 2001
APPROVED BY	TITLE	DATE
Conditions of approval, if any:		