

C1) wt



PHILLIPS PETROLEUM COMPANY

FARMINGTON, NEW MEXICO 87401
5525 HWY. 64 NBU 3004

RECEIVED
DEC 21 1998
OIL CON. DIV.
DOWE 21

December 29, 1998

NM Oil & Gas Conservation Division
Attn: Charlie T. Perrin
1000 Rio Brazos Road
Aztec, NM 87410

San Juan 30-5 Unit #84
J-33-30N, R5W, API 30-039-23019

Dear Mr. Perrin:

In reference to your letter dated December 21, 1998 about Packer Leakage Tests on the referenced well, we acknowledge your request to have the well remediated and retested to show separation of the two zones. We have several engineers gone till after the first of the year because of the holidays and there won't be anyone to review the well data until at least the week of the 4th. We would like to request at least another month to review well data and then try to secure a rig to do the workover.

Please call me at 599-3448 to let me if you will grant us another month to review the data on this well and have the work completed.

Sincerely,

PHILLIPS PETROLEUM COMPANY

A handwritten signature in cursive script that reads "Terry Bowker".

Terry Bowker
Well Tester