

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

P.O. Drawer 570, Farmington, New Mexico 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

890' FSL & 845' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether on the ground, map, or other source)

7104' G1

5. LEASE DESIGNATION AND SERIAL NO.

NM-13376

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Simms Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Blanco Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 36, T30N, R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

See Below

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

10/15/83 Subject well was sand water fraced (see sundry notice of 10-21-83).
Estimated load to recover 878 bbls.

10/20/83 to 10/27/83

MIRU Swabbing Unit. Started swabbing well. IFL 500', SITP 0 psi,
SICP 0 psi. Recovered 535 bbls water. Well tried to kick off once.
FFL 2900'. Final casing pressure 500 psi. Shut in for buildup.
343 BLTR.

11/04/83 to 11/05/83

MIRU Swabbing Unit. IFL 900'. SITP 0 psi, SICP 500 psi. Recovered
314 bbls wtr. Well showed no gas. FFL - swabbed dry. Final casing
pressure 125 psi. Shut in for pressure buildup.

02/17/84 SITP 75 psi, SICP 960 psi

Well is currently shut in pending attempt to potential test which could require
additional swabbing. Could not get Unit on location during February due to snow.
If potential test gives negative results, Southland will evaluate for possible
recompletion during the summer.

18. I hereby certify that the foregoing is true and correct

SIGNED

Esther Greger

TITLE

Secretary

DATE

5-01-84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

MAY 15 1984

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

RV