

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0125  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Exploratory Well - S.I. <b>Confidential Information</b>		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract #473	
2. NAME OF OPERATOR Union Oil Company of California		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR P. O. Box 2620 - Casper, WY 82602-2620		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements and Farmington Resource Area. See also space 17 below.) At surface 2300' FSL & 1875' FEL (NE NW SE)		8. FARM OR LEASE NAME Jicarilla (J21)	
14. PERMIT NO. API No. 30-039-23905		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 8204' GR (Ungraded)		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T.30N., R.1W.	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

FLOWED AND SWAB TESTED ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

4230' TD; 4178' ETD  
13-3/8" @ 417' w/550 sx cmt  
8-5/8" @ 3294' w/910 sx cmt  
5-1/2" L from 2963-4228' w/280 sx cmt

Drilled in 1986  
Perforated Niobrara formation  
w/1 spf w/3-3/8" select-fire  
gun (48 holes) from 3576-4034'

MIRU well testing unit on 5-11-87 and swab unit on 5-15-87. Flowed and swab tested Niobrara perforations for seven days, with initial FTP of 850 psi gradually decreasing to 5 psi and gas rate of 1146 MCF decreasing to 90.3 MCF. Recovered total of 4003 bbls. of 7318 bbl. water load with trace of oil. Last day of test, swabbed 2 bbls. water and zero bbls. oil in 5 hrs., with average gas rate of 90.3 MCFD, with tubing dry on second swab run. Released test unit on 5-19-87. N.D. Xtree. Installed BOP. POOH with tubing and packer. Preparing to plug and abandon well.

RECEIVED  
JUN - 4 1987  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED R. G. Ladd, Jr.

TITLE District Drilling Supt. ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE JUN 02 1987

FARMINGTON RESOURCE AREA

BY SWW

\*See Instructions on Reverse Side