rorm 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No. NMNM012573

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or	Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reve				OT 2002	NMNM78420B	ment, Name and/or No.
1. Type of Well	िंद ।		8. Well Name and No. SJ 30-6 401			
Oil Well Gas Well Oth Name of Operator	Roj Bos		33 30-6 401			
BURLINGTON RESOURCES	br (ae.com		30-039-24000-00-S1			
3a. Address P O BOX 4289 FARMINGTON, NM 87499	3b. Phone No. Ph: 505.326 Fx: 505.326		ode)	10. Field and Pool, or Exploratory BASIN FRUITLAND COAL		
4. Location of Well (Footage, Sec., T			11. County or Parish, and State			
Sec 13 T30N R7W NWSW 16 36.80986 N Lat, 107.52768 W				RIO ARRIBA COUNTY, NM		
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE	NATURE C	F NOTICE, R	EPORT, OR OTHER	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Nation of Intent	Acidize	Deep Deep	Deepen		ion (Start/Resume)	☐ Water Shut-Off
□ Notice of Intent	Alter Casing	□ Frac	☐ Fracture Treat		ation	☐ Well Integrity
Subsequent Report	Casing Repair		Construction	□ Recomp	olete	□ Other
☐ Final Abandonment Notice	☐ Change Plans	🛭 Plug	and Abandon	_	Temporarily Abandon	
13. Describe Proposed or Completed Ope	Convert to Injection	_	ig Back □ Water			
following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 9-10-02 MIRU. ND WH. NU E Retainer stuck. TOOH without tool. TOOH w/2800' 1/4" steel 9-11-02 TIH w/6 1/4" mill to c retainer to 2950'. TOOH w/mill csg to 500 psi, OK. SDON. 9-12-02 PT csg to 500 psi, O cover Fruitland Coal perfs. TC 2338-2379'. Rig pump failed. 9-13-02 (Tod Haanes, BLM o 62 sx Class "B" neat cmt insic 814'. Plug #4: pump 30 sx Class "B" steel pump 30 sx Class"	pandonment Notices shall be final inspection.) BOP. PT BOP. TOOH w/3 cmt retainer. Found 1/4' tbg. SDON. mt retainer @ 442'. Knoo I. TIH w/7" cmt retainer, s K. Plug #1: pump 28 sx C OOH to 2379'. Plug #2: pu Displace cmt. TOOH. SD In location). TIH, tag TOO le csg @ 2016-2321' to c	Bits 2 7/8" tbg stainless ster stainless ster ster @ 2919'. L class "B" neat ump 8 sx Class ON. c @ 2312'. PT	TIH w/7" cm el tbg wrappe se. Fell to 27 oad hole w/1 cmt inside co s "B" neat cn csg to 500 p	nt retainer to 44 ed around setting 80'. Push cmt 116 bbl wtr. PT sg @ 2777-291 nt inside csg @ ois, OK. Plug #3 intervals. TOO	n, have been completed, 2'. ng 7" 9' to 3: pump H to	and the operator has
	Electronic Submission i For BURLINGTON RI committed to AFMSS for pi	ESOURCES OF	kG CO LP, se teve Mason o	ent to the Farmir on 09/27/2002 (02	ngton 2SXM0425S)	
Name (Printed/Typed) PEGGY COLE			Title REC	SULATORY AD	MINISTRATOR	
Signature (Electronic S	Submission)		Date 09/2	6/2002		
	THIS SPACE FO	OR FEDERA	L OR STAT	TE OFFICE U	SE	
APPROVED By ACCEPTED			STEPH TitlePETR(STEPHEN MASON TitlePETROLEUM ENGINEER		Date 09/27/20
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.			Office Farmington person knowingly and willfully to make to any department or agency of the United			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it statements or representations a	a crime for any p is to any matter w	erson knowingly ithin its jurisdic	y and willfully to notion.	nake to any department of	ragency of the United

Additional data for EC transaction #14596 that would not fit on the form

32. Additional remarks, continued

Test bradenhead to 300 psi/15 min, OK. Plug #5: pump 30 sx Class "B" neat cmt inside csg @ 408-563' to cover 9 5/8" csg shoe. TOOH. TIH to 62'. Establish circ down csg & out csg valve. Plug #6: pump 17 sx Class "B" neat cmt down csg & out csg valve. Circ 1 bbl cmt to surface. TOOH. ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" neat cmt. RD. Rig released.

Well plugged and abandoned 9-13-02.