UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT	EEGÉTÄET.
Sundry Notices and Reports on	Wells
1. Type of Well GAS	9702031 PH 1:29 5. Lease Number SF-079382 OTO TTIBE Name
2. Name of Operator	7. Unit Agreement Name
BURLINGTON RESOURCES OIL & GAS COMPANY 3. Address & Phone No. of Operator	San Juan 30-6 Unit 8. Well Name & Number San Juan 30-6 U #41
PO Box 4289, Farmington, NM 87499 (505) 326-97	
4. Location of Well, Footage, Sec., T, R, M 1450'FSL, 1450'FWL, Sec.24, T-30-N, R-7-W, NMPM	10. Field and Pool Basin Fruitland Coa 11. County and State Rio Arriba Co, NM
Subsequent Report — Recompletion Subsequent Report — Plugging Back Casing Repair Final Abandonment — Altering Casin X Other - Recavi	<pre>Mon-Routine Fracturing Water Shut off Conversion to Injection</pre>
13. Describe Proposed or Completed Operations	
It is intended to recavitate the subject well Pull the production tubing. Pull the 5 1/2" l formation utilizing natural and air as stabilizes. Clean the well to total de casing liner. The liner will be pre-pe the coal intervals. Rerun the product: returned to production.	liner. Cavitate the Fruitland Coal ssisted surges until the well epth and run a 5 1/2" 15.5# K-55 erforated with 4 shots per foot across
	DECEIVED N JAN 1 2 1998
The data and for the formation in the same	OIL CON. DIV.
I hereby certify that the foregoing is true a signed lifty Mahaele (DWSFTC) Title Reg	gulatory Administrator Date 12/29/97
(This space for Dedge W. Speace Office use) APPROVED BY Title	Date JAN - 8 1998