

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF 079043	
2. NAME OF OPERATOR Blackwood & Nichols Co., Ltd.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1237, Durango, CO 81302-1237		7. UNIT AGREEMENT NAME Agreement No. I, Sec. 929	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1540' F/SL - 915' F/WL		8. FARM OR LEASE NAME Northeast Blanco Unit	
14. PERMIT NO. 30-039-24214		9. WELL NO. 401	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6299' U.G.		10. FIELD AND POOL, OR WILDCAT Basin Fruitland Coal	
12. COUNTY OR PARISH Rio Arriba		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA L-9-30N-7W	
13. STATE New Mexico			

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) Completion <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 9-13-88 Moved on and rigged up Drake Well Service. Pressure test BOP stack to 1000 PSI - held ok.
- 9-15-88 Ran GR-CCL-CBL from 2900' to 2000'; good bond. Tripped in hole with new 6 1/4" bit. Drilled cement to 7" casing shoe at 2949'. Drilled open hole section from 2949' to 3000'.
- 9-16-88 Drilled open hole to 3202'.  
Drilling Record: 2949' to 2965', shale; 2965' to 2967', coal; 2967' to 3018', shale; 3018' to 3024', coal (6'); 3024' to 3055', shale; 3055' to 3076', coal (21'); 3076' - 3086', shale; 3086' to 3088', coal (2'); 3088' to 3098', shale; 3098' to 3106', coal (8'); 3106' to 3164', shale; 3164' to 3177', coal (13'); 3177' to 3179', shale; 3179' to 3181', coal (2'); 3181' to 3185', shale; 3185' to 3191', coal (6'); 3191' to 3202', shale.
- 9-17-88 Run FDC/CNL. Loggers TD - 3106'. Bridge at 3106'. Worked through bridge to 3137. Stuck logging tool. Tool came free. Pull out of hole.  
CO fill to 3202', circulating with water. Stuck at 3192' while still circulating with water and working pipe. Worked pipe free. Pipe stuck again while circulating. Work pipe free. Stuck pipe at 3192'. Worked pipe free. Start to pull out of hole. Well quit circulating. Work pipe. Would come up but would not go down. Work pipe up to 3167'. Quit moving.
- 9-18-88 Drill string stuck.  
(continued on next page)

18. I hereby certify that the foregoing is true and correct

SIGNED William F. Clark

TITLE Operations Manager

DATE December 19, 1988

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

FRUITLAND RESOURCE AREA

BY Shm

\*See Instructions on Reverse Side