

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1535' FNL, 850' FWL, Sec. 11, T-30-N, R-7-W, NMPM

5. Lease Number  
NM-012694

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

San Juan 30-6 Unit  
8. Well Name & Number  
San Juan 30-6 U #84A  
9. API Well No.  
30-039-22651  
10. Field and Pool  
Blanco Mesaverde  
11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

|                                                       |                                                               |                                                  |
|-------------------------------------------------------|---------------------------------------------------------------|--------------------------------------------------|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Abandonment                          | <input type="checkbox"/> Change of Plans         |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion                         | <input type="checkbox"/> New Construction        |
| <input type="checkbox"/> Final Abandonment            | <input type="checkbox"/> Plugging Back                        | <input type="checkbox"/> Non-Routine Fracturing  |
|                                                       | <input type="checkbox"/> Casing Repair                        | <input type="checkbox"/> Water Shut off          |
|                                                       | <input type="checkbox"/> Altering Casing                      | <input type="checkbox"/> Conversion to Injection |
|                                                       | <input checked="" type="checkbox"/> Other - Bradenhead repair |                                                  |

13. Describe Proposed or Completed Operations

9-2-97 MIRU. ND WH. NU BOP. TOO H w/24 jts tbgs. PT secondary seal on tbgs head, OK. SDON.

9-3-97 TOO H w/rest of 2 3/8" tbgs. TIH w/4 1/2" csg scraper to 5750'. TOO H. TIH w/4 1/2" RBP, set @ 5005'. Load hole & circ clean. PT csg to 1000 psi/15 min, OK. Spot 8 gal sd on RBP. SDON.

9-4-97 TIH, ran CBL @ 0-1280' w/1000 psi, 90-100% bond @ 1050-1280, 60-80% bond @ 280-520'. TOO H. TIH w/retrieving tool to RBP @ 5005'. Circ hole clean. Release RBP, TOO H. TIH to 5000'. SDON.

9-5-97 Blow well & CO. TOO H. TIH w/181 jts 2 3/8" 4.7# J-55 EUE tbgs, landed @ 5669'. ND BOP. NU WH. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed *Regan Shanfield* Title Regulatory Administrator Date 9/8/97

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_

CONDITION OF APPROVAL, if any:

Date SEP 15 1997

FARMINGTON DISTRICT OFFICE  
2V *W*

NMOC