## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices	and Reports on Well	s p., y2: 53		
. Type of Well GAS	070 FAmili	5. 1991 (11) 1991 6.	SF-080713B	
2. Name of Operator		7.	Unit Agreement Name	
BURLINGTON	S COMPANY	8.	San Juan 30-6 Unit <b>Well Name &amp; Number</b>	
. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	San Juan 30-6 U #43 API Well No. 30-039-24242	
1. Location of Well, Footage, Sec., 900'FSL, 975'FWL, Sec.14, T-30-N,			Field and Pool Basin Fruitland Coa County and State Rio Arriba Co, NM	
Subsequent Report Final Abandonment	Type of Act Abandonment Recompletion Plugging Back Casing Repair	<pre>ion     Change of P     New Constru     Non-Routine     Water Shut     Conversion</pre>	lans ction Fracturing off	
3. Describe Proposed or Completed  It is intended to recavitate t		the following	manner:	
Pull the production tubing. Pu formation utilizing na- stabilizes. Clean the casing liner. The line across the coal interva- then be returned to pro-	tural and air assist well to total depth r will be pre-perfor als. Rerun the produ	ted surges unt and run a 5 f rated with 4 s	til the well 1/2" 15.5# K-55 Shots per foot	
		REGE FEB -	8 V E D	
		0][] [] [] []	N. DIV.	
A	DWSFTC) Title Regulat		ator, <u>Date</u> 1/30/98	
(This space for Steral or State Off APPROVED BY CONDITION OF APPROVAL, if any:	fice use)Title	Date	FEB - 5 1998	

