


VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT.

30-5 #239 WORKOVER PRODUCTION INCREASE



API #	30-5 #239	mcf/Month
30-039-25165	Aug-98	17,779
	Sep-98	21,777
	Oct-98	21,588
	Nov-98	20,379
	Dec-98	21,443
	Jan-99	20,436
	Feb-99	19,493
	Mar-99	21,284
	Apr-99	20,470
	May-99	25,832
	Jun-99	25,664
	Jul-99	27,174
	Aug-99	29,078
	Sep-99	21,007
	Oct-99	27,806
	Nov-99	26,855
	Dec-99	29,584
	Jan-00	28,652
	Feb-00	26,497
	Mar-00	27,981
	Apr-00	25,525

**San Juan 30-5 Unit #239
SF-078994; API # 30-039-25165
Unit M, 926' FSL & 1171' FWL
Section 15, T30N, R5W; Rio Arriba County**

Description of workover procedure used to increase production on subject well:

A compressor was installed and the work entailed:

1. Taking existing surface equipment off.
2. Replacing old equipment with bigger equipment, (i.e.. bigger separator and flow lines).
3. Installing compressor manifold.
4. Debottlenecking location – eliminating any restrictions between wellhead and meter run.
5. Installing compressor and hooking up.

The type of compressor installed is a Cooper 305 hp. Work began approx. 7/30/99 and was completed 8/4/99.