



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

September 20, 2001

Dolores Silseth
Burlington Res. O&G Co.
PO Box 4289
Farmington NM 87499

Re: San Juan 30-6 Unit # 92A, I-33-30N-07W, API 30-039-25409

Dear Ms. Silseth:

The 2001 Packer Leakage Test on the referenced well indicates the pressure in the lower zone had not stabilized, number 3 on the back of the Northwest New Mexico Packer-Leakage Test Form

...Both zones shall remain shut-in until the wellhead pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.

You are hereby directed to conduct a Packer Leakage test to show separation of the zones prior to November 25, 2001.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: BLM
CTP
Well File