UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sund	ry Notices and Reports on Wells		
		5.	Lease Number
. Type of Well		6.	
		7.	Unit Agreement Name
. Name of Operator	_		
BURLINGTO! RESOURCES	V		0 Turn 20 6 Hait
RESCERCES	OIL & GAS COMPANY	8.	San Juan 30-6 Unit Well Name & Number
. Address & Phone No. of	Operator		San Juan 30-6 U #5A
PO Box 4289, Farmingt	con, NM 87499 (505) 326-9700	9.	API Well No. 30-039-25595
. Location of Well, Foot	age, Sec., T, R, M	10.	Field and Pool
1810'FNL, 1810'FWL, Se	ec.35, T-30-N, R-6-W, NMPM	11.	Blanco Mesaverde County and State Rio Arriba Co, NM
X Subsequent Rep		on-Routine	
Final Abandonm 3. Describe Proposed of 10-12-96 MIRU. Spu TIH w/5 w/3% cal	Casing Repair Altering Casing C X Other - Spud C C Completed Operations Id well @ 4:45 p.m. 10-12-96. Dril jts 9 5/8" 36# K-55 ST&C csg, set Cium chloride, 0.25 pps Flocele (WOC.	l to 245'. @ 239'. Cm 187 cu.ft).	Circ hole clean. TOO td w/163 sx Class "B" Circ 10 bbl cmt to
Final Abandonm 13. Describe Proposed of 10-12-96 MIRU. Spu TIH w/5 w/3% cal	Casing Repair When Altering Casing Completed Operations and well @ 4:45 p.m. 10-12-96. Drill jts 9 5/8" 36# K-55 ST&C csg, set cium chloride, 0.25 pps Flocele (l to 245'. @ 239'. Cm 187 cu.ft).	Circ hole clean. TOO td w/163 sx Class "B" Circ 10 bbl cmt to
Final Abandonm 13. Describe Proposed of 10-12-96 MIRU. Spu TIH w/5 w/3% cal	Casing Repair W Altering Casing C X Other - Spud Or Completed Operations Ind well @ 4:45 p.m. 10-12-96. Drill jts 9 5/8" 36# K-55 ST&C csg, set Cium chloride, 0.25 pps Flocele (WOC. BOP. PT BOP & csg to 600 psi/30 mi	l to 245'. @ 239'. Cm 187 cu.ft). m, OK. Dril	Circ hole clean. TOO td w/163 sx Class "B" Circ 10 bbl cmt to
Final Abandons 13. Describe Proposed of 10-12-96 MIRU. Sputification of the first surface. 10-13-96 WOC. NU Fig. 10-13-96 WOC. NU Fig. 10-13-96 WOC.	Casing Repair Waltering Casing	l to 245'. @ 239'. Cm 187 cu.ft). n, OK. Dril	Circ hole clean. TOO td w/163 sx Class "B Circ 10 bbl cmt to
Final Abandons 13. Describe Proposed of 10-12-96 MIRU. Sputification of the first surface. 10-13-96 WOC. NU Fig. 14. I hereby certify the surface of the first surface of the first surface.	Casing Repair Waltering Casing	l to 245'. @ 239'. Cm 187 cu.ft). n, OK. Dril	Circ hole clean. TOO td w/163 sx Class "B Circ 10 bbl cmt to
Final Abandons 13. Describe Proposed of 10-12-96 MIRU. Sput TIH w/5 w/3% call surface. 10-13-96 WOC. NU F	Casing Repair Waltering Casing Casi	l to 245'. @ 239'. Cm 187 cu.ft). n, OK. Dril	Circ hole clean. TOO td w/163 sx Class "B Circ 10 bbl cmt to

FARMINGTON DISTRICT OFFICE

BY 443