UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

And the second s		
Sundry Notices and Reports on Wells		
. Type of Well GAS	5. 6.	Lease Number NM-012694 If Indian, All. or Tribe Name
	7.	Unit Agreement Name
. Name of Operator		
RESOURCES OIL & GAS COMPANY	8.	San Juan 30-6 Unit Well Name & Number San Juan 30-6 U #83A
B. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	
4. Location of Well, Footage, Sec., T, R, M 2530'FSL, 2315'FEL, Sec.15, T-30-N, R-7-W, NMPM	10.	Field and Pool Blanco Mesaverde
#5	11.	County and State Rio Arriba Co, NM
		RIO RILIDA CO, IM
Subsequent Report Subsequent Report Plugging Back Casing Repair Wat Altering Casing Con X Other Due to lost circulation in the Fruitland Coal, the apprendent procedure will be changed to a two stage will be set 50' above the Fruitland Coal format First stage: lead with 39 sacks 65/35 Class "B chloride, 0.25 pps Cellophane, 5 pps Gilsonite cement with 2% calcium chloride, 0.25 pps Cellophane, 5 pps Cel	proved sine cement sin	gle stage intermediate procedure. The stage too 17'. with 6% gel, 2% calcium th 100 sacks Class "B" 90 cubic feet, 100%
chloride, 0.25 pps Cellophane, 5 pps Gilsonite with 2% calcium chloride, 0.25 pps Cellophane	. Tail wit	th Class "B" heat cement c feet, 100% excess).
Verbal approval to change plans from Errol Becher, BLM	4 on 11-1-	90.
14. I hereby certify that the foregoing is true and correct Signed May Stadhuld Title Regulatory Administration		e 11/5/96
(This space for Federal or State Office use)	Date	
APPROVED BYTitle CONDITION OF APPROVAL, if any:		APPROVED
		New 0 & 1996