## UNITED STATES

## DEPARTMENT OF THE INTERIOR

BURKAU	OF	LAND	MANAGEMEN	T ~

	OF LAND MANAGEMENT RECEIVED		
Sundry Not:	ices and Reports on Wells		
	97 AUG -7 AHH: 20	5.	Lease Number
		٥.	SF-080714A
1. <b>Type of Well</b> GAS	070 FARMINGTON, NM	6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Nam
2. Name of Operator			
BURLINGTON RESOURCES			
oil oil	& GAS COMPANY	8.	San Juan 30-6 Unit Well Name & Number
3. Address & Phone No. of Operat	tor	ъ.	San Juan 30-6 U #4
PO Box 4289, Farmington, NM 87499 (505) 326-9700			API Well No.
4. Location of Well, Footage, Se	10.	30-039-25637 Field and Pool	
790'FNL, 1700'FWL, Sec. 15, T-30-N, R-6-W, NMPM			Blanco MV/Basin DK
		11.	County and State Rio Arriba Co, NM
The intermediate of with 2% gel foamed with 0.5% versaset annulus with 40 sa	Recompletion New Con Plugging Back Non-Rou Casing Repair Water S Altering Casing Convers X Other -  leted Operations  the intermediate cementing design casing will be cemented with 360 s with nitrogen. Tail with 50 sacks with 2% calcium chloride. Cement acks Class "G" cement w/0.5% versa approval to change plans from Erro	tine in the ion to sacks as Cla	Fracturing  ff  o Injection  he subject well.  Class "G" 50/50 poz  iss "G" cement  be capped down the  ith 2% calcium
			JANUAN 1 1 2 1987 P
			COM. DIW. Dist. 3
14 I hereby certify that the	foregoing is true and correct.	The second of the	
signed (Myy) /the ful	Title Regulatory Administrato	r_Dat	e 8/6/97
(This space for Federal or State APPROVED BY		te _	AUG 0 8 1997