

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1800' FNL, 1520' FEL, Sec. 28, T-30-N, R-6-W, NMPM

5. Lease Number

NMSF-080712A

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

San Juan 30-6 Unit

8. Well Name & Number

San Juan 30-6 U #130

9. API Well No.

30-039-26216

10. Field and Pool

La Jara Pict. Cliffs

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☒ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☐ Other -

13. Describe Proposed or Completed Operations

5-2-02 MIRU. ND WH. NU BOP. PT BOP. TOO H w/103 jts 2 3/8" tbg. TIH, tag existing CIBP @ 3260'. Load hole w/60 bbl wtr. Unable to establish circ. (Jimmy Morris, BLM on location for cementing). Plug #1: pump 34 sx Class "B" neat cmt inside csg @ 2812-3260' to cover Pictured Cliffs & Fruitland perms. TOO H to 2150'. WOC. SDON.

5-3-02 (Jimmy Morris, BLM on location). TIH, tag TOC @ 3228'. Plug #2: pump 54 sx Class "B" neat cmt inside csg @ 2516-3228' to cover Fruitland perms. TOO H to 1880'. WOC. Pump 8 bbl wtr down bradenhead. Establish injection. TIH, tag TOC @ 2670'. PT csg to 500 psi, OK. TOO H to 2564'. Plug #3: pump 31 sx Class "B" neat cmt inside csg @ 2156-2564' to cover Kirtland & Ojo Alamo intervals. TOO H to 1125'. Plug #4: pump 12 sx Class "B" neat cmt inside csg @ 967-1125' to cover Nacimiento interval. TOO H. WOC. SD for weekend.

5-6-02 TIH, perf 3 sqz holes @ 193'. TOO H. Establish circ down csg & out bradenhead w/2 bbl wtr. Plug #5: pump 80 sx Type II cmt down 4 1/2" csg & out bradenhead valve. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" neat cmt. RD. Rig released.

Well plugged and abandoned 5-6-02.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Supervisor Date 5/14/02

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date ACCE-10 FOR RECORD

CONDITION OF APPROVAL, if any:

29 2002

NMOGE

Smg OFFICE