



Key Energy Services, Inc.

Four Corners Division
5651 US Highway 64
P.O. Box 900
Farmington, NM 87499

Phone: 505-327-4935
Fax: 505-327-4962

January 02, 2001

Rig No. 47

Phillips Petroleum Company
5525 Hwy 64 NBU 3004
Farmington, NM 87401

Attn: Patsy Clugston

J-24-30N-6W 039-26513


This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 30-6 #35A well in S27-T27N-R03W, in San Rio Arriba, New Mexico.

Depth	Deviation	Depth	Deviation
155'	$\frac{3}{4}^{\circ}$	3163'	1°
339'	$\frac{3}{4}^{\circ}$	3631'	$\frac{3}{4}^{\circ}$
648'	$1\frac{3}{4}^{\circ}$	3959'	$\frac{1}{2}^{\circ}$
1168'	$1\frac{1}{4}^{\circ}$	4458'	$\frac{3}{4}^{\circ}$
1667'	$1\frac{3}{4}^{\circ}$	5047'	$1\frac{1}{4}^{\circ}$
2163'	$1\frac{3}{4}^{\circ}$	5554'	$1\frac{3}{4}^{\circ}$
2663'	$\frac{1}{2}^{\circ}$	5948'	2°

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager



Lucas M. Luesgore
Notary Public

My commission expires: 6/26/02