

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
State E-9230

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Aztec Oil & Gas Company	8. Farm or Lease Name Southeast Cha Cha
3. Address of Operator P. O. Drawer 570, Farmington, New Mexico	9. Well No. #1
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>29N</u> RANGE <u>13W</u> NMPM.	10. Field and Pool, or Wildcat Totah Gallup
15. Elevation (Show whether DF, RT, GR, etc.) 5933'	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSE TO:

- (1) Pull 2-3/8" Tubing.
- (2) Squeeze Perforations From 5645' To 5652', 5587' To 5594'.
- (3) Spot Plug From 100' Below Pictured Cliff To 100' Above Pictured Cliff.
- (4) Set 10 Sack Plug @ surface.
- (5) Install Dry Hole Marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe C. Harmon</u>	TITLE <u>District Superintendent</u>	DATE <u>November 1, 1973</u>
APPROVED BY <u>Quincy C. Chumley</u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>NOV 5 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		