UNITED STATES

DEPARTMENT OF THE INTERIOR

	Sundry No.	tices and Reports on Well	1:30	
		- 9 1907	5. Le	ease Number 7-047020A F Indian, All. or
1. T	rpe of Well GAS	- 9 1997 070 (77) (17) (17) (17) (18) (18)	T:	ribe Name
		ON. DIV. ISL 3	7. Ur	nit Agreement Name
2. Na	me of Operator	& GAS COMPANY		
				ell Name & Number
	ddress & Phone No. of Oper			ongress #3
]	PO Box 4289, Farmington, N	M 87499 (505) 326-9700		PI Well No. 0-045-07618
1 T.,	ocation of Well, Footage,	Sec., T. R. M		ield and Pool
	90'FSL, 990'FWL, Sec. 35, T			ulcher Kutz PC
	, , , , , , , , , , , , , , , , , , , ,	,	11. Co	ounty and State
T:	K-273		Sa	an Juan Co, NM
	X Subsequent Report	Plugging Back	Non-Routine Fra	cturing
	Final Abandonment	Casing Repair Altering Casing X Other - Restimulat		injection
L3.	Final Abandonment Describe Proposed or Com	Altering Casing _X_ Other - Restimulat	Conversion to I	injection
.3.	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Company of the company o	Altering CasingX_Other - Restimulate pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND	Conversion to I e RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released.
13.	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Co 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/	Altering CasingX_Other - Restimulate	Conversion to I e RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released. Pictured Cliffs @
L3.	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Com 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/ Pictured Clift frac. 11-8/17-97 Blow well &	Altering CasingX_Other - Restimulate pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND U BOP. TIH, ran CCL-GR @ 8 0.31" diameter holes to fs w/681 bbl 25# linear g	RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20 el, 244,000# 20/4	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released. Pictured Cliffs @
L3.	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Com 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/ Pictured Clift frac. 11-8/17-97 Blow well &	Altering Casing X Other - Restimulate Pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND U BOP. TIH, ran CCL-GR @ 8 0.31" diameter holes to fs w/681 bbl 25# linear g	RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20 el, 244,000# 20/4	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 184! magnet. TOOH. SDON Rig released. Pictured Cliffs @
13.	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Co 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/ Pictured Clif frac. 11-8/17-97 Blow well & 11-18-97 Blow well & CO	Altering Casing X Other - Restimulate pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND U BOP. TIH, ran CCL-GR @ 8 0.31" diameter holes to fs w/681 bbl 25# linear g CO ND BOP. NU WH. RD. Rig	RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20 el, 244,000# 20/4 released.	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released. Pictured Cliffs @
14 Sign	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Co 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/ Pictured Clif frac. 11-8/17-97 Blow well & 11-18-97 Blow well & Co	Altering Casing X Other - Restimulate pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND U BOP. TIH, ran CCL-GR @ 8 0.31" diameter holes to fs w/681 bbl 25# linear g CO ND BOP. NU WH. RD. Rig Title Regulatory Adr	RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20 el, 244,000# 20/4 released.	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released. Pictured Cliffs @
14 Sign	Describe Proposed or Com 10-22-97 MIRU. ND WH. N 10-23-97 TOOH w/57 jts Attempt to PT OK. TOOH. TIH Blow well & Co 10-24-97 TIH w/fishing 11-7-97 MIRU. ND WH. N 1814-1821' w/ Pictured Clif frac. 11-8/17-97 Blow well & 11-18-97 Blow well & CO	Altering Casing X Other - Restimulate pleted Operations U BOP. SDON. 1 1/2" tbg. TIH w/3 1/2" RBP. TOOH. Load hole w/w w/retrieving tool. Latch O. TOOH w/bit. Pin had tw tools. Fishing. TOOH. ND U BOP. TIH, ran CCL-GR @ 8 0.31" diameter holes to fs w/681 bbl 25# linear g CO ND BOP. NU WH. RD. Rig Title Regulatory Adr	RBP, set @ 1788'. tr. PT 3 1/2" csg RBP, TOOH. TIH w isted off. TIH w/ BOP. NU WH. RD. R 1400-1842'. Perf tal. Acidize w/20 el, 244,000# 20/4 released.	Load hole w/wtr. to 5000 psi/15 min /bit, tag up @ 1845 magnet. TOOH. SDON. Rig released. Pictured Cliffs @