



LOG OF OIL OR GAS WELL

LOCATE WELL CORRECTLY

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

The summary on this page is for the condition of the well at above date.

Commented drilling March 30, 1964 Finished drilling April 5, 1964

(Denote gas by G)

IMPORTANT WATER SANDS

CASING RECORD

MUDDING AND CEMENTING RECORD

FOLD | MARK

Heaving plug—Material Length Depth set

Adapters—Material Size

[illegible]

Rotary tools were used from 0 feet to 4267 feet, and from feet to feet
Cable tools were used from feet to feet, and from feet to feet

_____, 19____ Put to producing _____, 19____

The production for the first 24 hours was ----- barrels of fluid of which -----% was oil; -----% emulsion; -----% water; and -----% sediment.

Gravity, °Bé. -----

If gas well, cu. ft. per 24 hours Gallons gasoline per 1,000 cu. ft. of gas

Rock pressure, lbs. per sq. in. -----

~~Exeter Drilling Company~~, Driller _____, Driller _____
_____, Driller _____, Driller _____

FROM--	TO--	TOTAL FEET	FORMATION
0'	3930'	3930	Sand & shale
3930'	3965'	35	Core No. 1
3965'	4267'	302	Sand & shale
<u>Core No. 1 - 3930' - 3965' - Cut & Rec. 35'</u>			
20' - Sandstone, gray to brown gray, very fine to fine grain with irregular shale partings, with laminations carb. material.			
1' - Siltstone, dark gray, sandy.			
2' - Sandstone, gray, very fine grain with black shale inclusions.			
12' - Siltstone, dark gray. Became increasingly calcareous at base. No show, no odor.			

FROM-	TO-	TOTAL FEET	FORMATION

Log Tops:

Climb House	1,380'	(+4009)
Menefee	1,440'	(+3945)
Pt. Lookout	2,460'	(+2929)
Mancos	2,768'	(+2621)
Upper Gallup	3,712'	(+1677)
Lower Gallup	4,010'	(+1379)
Sanastee	4,163'	(+1226)

Ping No. 1	- 4213	- 4113	- 100'	- 33	sax reg. cement.
Ping No. 2	- 3980	- 3880	- 100'	- 33	sax reg. cement.
Ping No. 3	- 2818	- 2718	- 100'	- 33	sax reg. cement.
Ping No. 4	- 10	sax reg. cement in top of 9-5/8" surface casing.			

9.7' mud left between cement plugs. Dryhole marker installed in accordance with U.S.G.S. regulations.