X

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau No. 42 R358.4. Form Approved.
Land Office Sanca Te
Lease No. 078931-B
Unit

NOTICE OF INTENTION TO DRILL		IBSEQUENT REPORT OF WATER SHUT-OFF] -
NOTICE OF INTENTION TO THEE WATER CHUT OFF		BSEQUENT REPORT OF SHOOTING OR ACIDIZING	1
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		BSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		BSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		BSEQUENT REPORT OF ABANDONMENT	-
NOTICE OF INTENTION TO PULL OR ALTER CASING		PPLEMENTARY WELL HISTORY	1
NOTICE OF INTENTION TO ABANDON WELL.			Ī
Notice of Intention to Convert to	<u> </u>		
Water Supply Wellindicate above by CHECK MAR	RK NATURE	OF REPORT, NOTICE, OR OTHER DATA)	
			9
Well No. 2 is located 890 ft. from	m [N]	(=)	
NE/4 Section 33 29 N	13 W	n.m.p.n.	
(½ Sec. and Sec. No.) (Twp.)	(Range)	(Meridian)	
West Kuts Canyon P.C. San Juan		New Mexico	
(Field) (County	or Subdivis	sion) (State or Territory)	
The elevation of the derrick floor above sea le		5848 ft. F WORK	
(State names of and expected depths to objective sands; show si ing points, and all	izes, weight	ts, and lengths of proposed casings: indicate mudding jobs, cemen	
	other impo	ortant proposed work)	t-
1. Spot 25 ax cement, 2% CaCle with hole from 1561-1596.		ortant proposed work) be. walnut bulls per eack in open	t-
		ortant proposed work)	t-
hole from 1561-1596. 2. WCC.		ortant proposed work)	t-
hole from 1561-1596.		ortant proposed work)	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test.		ortant proposed work)	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac.		ortant proposed work)	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test.		be. walnut hulls per sack in open	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac.		be. walnut hulls per sack in open	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test.		De. welnut hulls per sack in open RECEIVED MAY3 1962	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test.		Per sack in open RECEIVED MAY3 1962 OIL CON. COM.	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test.		De. welnut hulls per sack in open RECEIVED MAY3 1962	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test.		Per sack in open RECEIVED MAY3 1962 OIL CON. COM.	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location.	th 3 11	Per sack in open RECEIVED MAY3 1962 OIL CON. COM.	t-
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location. I understand that this plan of work must receive approval in	th 3 11	Pos. welmut hulls per sack in open RECEIVED MAY3 1962 OIL CON. COM. DIST. 3	
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location. I understand that this plan of work must receive approval in	th 3 11	per sack in open RECEIVED MAY3 1962 OIL CON. COM. DIST. 3 y the Geological Survey before operations may be commenced.	
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location. I understand that this plan of work must receive approval in Company Tennaco Corp., acting by & d. Address P. O. Box 1714	th 3 11	PECELVED RECEIVED MAY3 1962 OIL CON. COM. DIST. 3 The Geological Survey before operations may be commenced. The managing agent, Tenneco Cil Company	
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location. I understand that this plan of work must receive approval in Company Tennaco Corp., acting by & to the company Tennaco Corp.	th 3 11	per sack in open RECEIVED MAY3 1962 OIL CON. COM. DIST. 3 y the Geological Survey before operations may be commenced.	
hole from 1561-1596. 2. WCC. 3. Drill to 1715. 4. Swab test. 5. If necessary, sand-water frac. 6. Clean out and swab test. 7. Clean up location. I understand that this plan of work must receive approval in Company Tennaco Corp., acting by & d. Address P. O. Box 1714	th 3 11	PECELVED RECEIVED MAY3 1962 OIL CON. COM. DIST. 3 The Geological Survey before operations may be commenced. The managing agent, Tenneco Cil Company	