

(SUBMIT IN TRIPLICATE)

Form approved.
Budget Bureau No. 42-R359.4.

Indian Agency Window Rock, Ariz.

| | |
|-----------|--|
| Sec. 36 | |
| 129N R10W | |
| | |
| | |

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Navajo
Allottee Navajo Tract #23
Lease No. 14-20-603-5025

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|--|----------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | <u>Subsequent Report for Setting 7"</u> | |
| | <u>Intermediate Casing</u> | <u>X</u> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 1963

Well No. 1 is located 1900 ft. from [N] line and 1900 ft. from [E] line of sec. 36

NW SE, Sec. 36
(1/4 Sec. and Sec. No.)

29N
(Twp.)

10W
(Range)

NMPM
(Meridian)

Pajarito Area
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5247' ft.

JUL 3 1963

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

6/29/63 - Present Depth 6197':

Ran 11 jts. 7" 23# N-80 R-3 and 144 jts. 7" 23# J-55 R-3 csg. for total of 6182'. Set @ 6196' w/Hall. float shoe on btm. & Hall. float collar @ 6156'. Ran 6 centralizers. Cemented by Halliburton w/150 sacks 50-50 Pozmix Cement w/2% Gel. Pumped plug to 6156', pressured up to 1500# - Held Ok.

Note: Had to run intermediated string to shut off water flow and lost circulation zones. If well is dry hole, we will pull intermediated string above cement.

Drilling ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amerada Petroleum Corporation

Address Box 1469

Durango, Colorado

247-5353

By D. E. Holbrook

Title Foreman



