

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2172

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

NW Cha Cha

8. FARM OR LEASE NAME

NW Cha Cha Unit

9. WELL NO.

12-35

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 35-29N-14W NMMPM

12. COUNTY OR PARISH

San Juan

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Humble Oil & Refining Company

3. ADDRESS OF OPERATOR
P. O. Box 120, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

SW NE (1980' FNL, 660' FWL) Sec. 35

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5841 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-21-72 Spot 12 sxs cement plug from 5415-5300.

10-25-72 Shot Casing @ 1500'. Pump 30 sxs cement plug. Left top of plug inside casing @ 1450'. Shot casing off @ 1294 and pulled casing.

10-27-72 Spot 30 sack cement plug from 1350 to 1200'.

Spot 30 sack cement plug from 259 to 157.

Spot 10 sack cement plug from 30' to surface.

Installed regulation dry hole marker and cleaned location for inspection.

Intervals between plugs filled with gelled mud.

CC: 2-New Mexico Oil Conservation Commission
1-Minerals Supervisor-Navajo Tribe
1-Midland

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Roy Dorrrough

TITLE District Superintendent

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side