NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

(Form C-104) Revised 7/1/57

REQUEST FOR (GAS) ALLOWABLE

Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

Tenneco Oil Company				Helen		, Well No	. 1 , i	nNE	1/4
		y or Oper		20.14	(Lease)				
Timit	A	, Sec	34	., Т29-и	, R. 9-W	, NMPM., Bl	NCO Mes	averde	Pc
Sen	Juan					5-9-52 De			
P	lease inc	dicate lo	ration:			Name of Pro			
D	C	В	A	PRODUCING INT					······································
			X			man aida			
E	F	G	Н		See reve	Denth		Depth	1
- I	_			Open Hole		Casing Shoe		Tubing_	4500"
		<u> </u>		OIL WELL TEST	<u> </u>				6)
L	K	J	I	Natural Prod	Test:	bbls.oil,	bbls water	inhrs,	Chol min∙ Size
						Treatment (after reco			
M	N	0	P			ls.oil,bbls			Choke
		<u></u>		GAS WELL TEST	=				
						MCF/Day; Ho			
ıbing ,	Casing a	and Cemen	ting Recor	d Method of Te	sting (pitot, ba	ack pressure, etc.):			
ibling ,	•	and Gemen	_	d Method of Te	sting (pitot, ba	ack pressure, etc.):			
Size		Feet	Sax	Method of Tes	sting (pitot, ba		A		
			_	Method of Test Test After Ac Choke Size	sting (pitot, bacid or Fracture Open Method of	Treatment: 3758 of Testing: Pitot	Tube	MCF/Day; Hours	s flowed 24
Size		Feet	Sax	Method of Test Test After Ac Choke Size Acid or Fract	sting (pitot, bacid or Fracture Open Method of Sure Treatment (Treatment: 3758 of Testing: Pitot Give amounts of mater	Tube	MCF/Day; Hours	s flowed 24
Size		Feet	Sax	Method of Test Test After Ac Choke Size Acid or Fract sand):	cid or Fracture Open Method of Cure Treatment (Treatment: 3758 of Testing: Pitot Give amounts of mater	Tube	MCF/Day; Hours	s flowed 24
Size		Feet	Sax	Method of Test Test After Ac Choke Size Acid or Fract sand): Casing	cid or Fracture Open Method of Cure Treatment (See reverse Tubing	Treatment: 3758 of Testing: Pitot Give amounts of mater	Tube	MCF/Day; Hours	s flowed 24
Sure		4550	Sax	Method of Test Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport	cid or Fracture Open Method of Cure Treatment (See reverse Tubing Press.	Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks	Tube	MCF/Day; Hours	s flowed 24
Sure He		4550	Sax	Method of Test Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport	cid or Fracture Open Method of Cure Treatment (See reverse Tubing Press.	Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks	Tube	MCF/Day; Hours	s flowed 24
*2-£	Stages	4550	\$400#	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	cid or Fracture Open Method of See reverse Tubing Press. ter Souther	Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Gather	ials used,	MCF/Day; Hours	water, oil, a
*2-£	Stages	4550	\$400#	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	cid or Fracture Open Method of See reverse Tubing Press. ter Souther	Treatment: 3758 Of Testing: Pitot Give amounts of mater Bide Date first new oil run to tanks Pern Union Gather	ials used,	MCF/Day; Hours	water, oil, a
*2-£	Stages	4550	\$400#	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	cid or Fracture Open Method of See reverse Tubing Press. ter Souther	Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Gather	ials used,	MCF/Day; Hours	water, oil, a
Sure 42 *2-5	Stages Well	4550 conne	Sax 400*	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	or Fracture Open Method of Over Treatment (See reverse Tubing Press. ter Souther L1/25/64.	Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Cather	ials used,	MCF/Day; Hours	water, oil, a
#2-5	Stages Well ereby ce	conne	Sax 400*	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	open Method of Treature Open Method of Treatment (See reverse Tubing Press. ter Souther L1/25/04.	Treatment: 3758 Treatment: 3758 Pitot Give amounts of mater Bide Date first new oil run to tanks Pern Union Gather and complete to the boreneco	ials used, ials com est of my k	CF/Day; Hours such as acid,	water, oil, a
2=£	Stages Well ereby ce	4550 conne	Sax 400	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	open Method of Treature Open Method of Treatment (See reverse Tubing Press. ter Souther L1/25/04.	Treatment: 3758 Treatment: 3758 Pitot Give amounts of mater Bide Date first new oil run to tanks Pern Union Gather and complete to the boreneco	ials used,	CF/Day; Hours such as acid,	water, oil, al
#2-5	Stages Well ereby ce	conne	Sax 400* eted to	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	or Fracture Open Method of See reverse Tubing Press. ter Souther above is true a	Treatment: 3758 Treatment: 3758 Pitot Give amounts of mater Bide Date first new oil run to tanks Pern Union Gather and complete to the boreneco	ials used, ials used, ing Com est of my k ill Comp	such as acid,	water, oil, at the control of the co
#2=6 marks	Stages Well ereby ce	conne	t the info	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport Sales line COMMISSIO	See reverse Tubing Press. ter Souther 11/25/64	Treatment: 3758 Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Cather and complete to the b Tenneco	ials used, ials used, cing Company of Comp	such as acid, such as acid, anowledge. Cl	water, oil, at the control of the co
#2=6 marks	Stages Well ereby ce	conne	t the info	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	See reverse Tubing Press. ter Souther 11/25/64	Treatment: 3758 Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Gather and complete to the bore Tenneco G	est of my k	such as acid, such as acid, nowledge.Cl	water, oil, and water, oil, an
#2-8	ereby ce	conne	t the info	Test After Ad Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport Sales line COMMISSIO	See reverse Tubing Press. ter Souther 11/25/64	Treatment: 3758 Treatment: 3758 of Testing: Pitot Give amounts of mater side Date first new oil run to tanks ern Union Gather and complete to the bore Tenneco G	est of my k	such as acid, such as acid, anowledge. Cleany Operator) atture) a Clerk	water, oil, ar Water, oil, ar LCON. CO DIST. 3 G. A. Porc

Perf v/4 holes per ft. 4505-06, 4481-82, 4463-64, 4445-46, 4434-35, 4419-20, 4403-04, 4288-89, 4255-56, 4241-42.

Prac v/81,060 gals. water, 75,000# 10-20 sand.

Perf w/4 holes per ft. 4152-53, 4035-36, 4002-03, 3989-90, 3940-41, 3868-69, 3848-49, 3834-35.

Frac w/76,109 gals. water, 75,000# 10-20 sand.

f=c+	<u> </u>	•	
STATE	OF NEW	MEXICO	
OIL COX5	KYATIO, I	1.1% (3	0.,
NUMBER OF COP	DISTRICT	OFFICE	
D.	STILL) *	
SANTA FE			ı =====
U.S.G.S. LAND GFFICE			_
TRANSPORTER	OIL		
PRORATION OFFICE	GAS		
OPERATOR		7	