



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SW 080247
Unit 8/2 Sec. 25

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REPAIR OR REPAIR..... <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 29, 1956

Fluoresce

Well No. 26 is located 990 ft. from [S] line and 990 ft. from [W] line of sec. 25

SW 1/4 Sec. 25
(1/4 Sec. and Sec. No.)

29N
(Twp.)

9W
(Range)

107W
(Meridian)

Blanco (Manzanita) (FE)
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5920 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After packer leakage tests indicated communication between the tubing & casing and a directive from EMCC that remedial steps be taken immediately to separate the PC and MS zones. Both strings of tubing were removed from well and it was found that free sand from perforation in 9 5/8" casing thru the PC. Jetting against 2 1/2" tubing had cut a small hole in the tubing. Entire string of 2 1/2" tubing was replaced with new pipe and both strings re-run in well.

Now SI awaiting re-test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Balbi-Taylor Oil Corporation

Address P. O. Box 1175

Farmington, New Mexico

By J. P. Harnell

Title Dist. Supt.

