

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	RECEIVED FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO JAN 11 11:34	3. LEASE DESIGNATION AND SERIAL NO. SF 079065
2. NAME OF OPERATOR Southland Royalty Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790'S, 790'E		8. FARM OR LEASE NAME Hagood
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, BT, OR, etc.)	9. WELL NO. 5
		10. FIELD AND POOL, OR WILDCAT Basin Dakota
		11. SEC., T., R., N., OR S.W. 1/4, AND SURVEY OR AREA Sec. 29, T-29-N, R-12-W N.M.P.M.
		12. COUNTY OR PARISH 13. STATE San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Ric JAN 07 1988

12-22-87 MOL&RU. NU BOP. SDFN.
12-23-87 1 1/2" tbg. stuck in hole. Pull to 30,000#, still stuck. Ran wireline to 5000'. SDFN.
12-24-87 Pulled 40,000#, would not come loose. Backed off, rec. 88 jts.
12-25-87 SD for holidays.
12-28-87 TIH w/overshot w/ 2 3/8" fishing string. Pulled tbg. loose. Rec. 181 jts. 1 1/2" IJ tbg. Latch back into remaining tbg. SDFN.
12-29-87 Set cement plug from 6000-5360'. Set plug from 5273-5170'.
12-30-87 Shot 4 holes @ 3190'. Squeeze w/ 20 sx. cmt. into formation. Set plug 3190-3090'. Set cement plug 1600-1500'. Set cement plug 1258-1158'. Shot 4 holes @ 610'. Squeezed 210 sx. into formation. Returns to surface. Cut off wellhead, set dry hole marker.

After the completion of the well, the well is to be plugged and the well is to be abandoned.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Drilling Clerk</u>	DATE <u>12-31-87</u>
---------------------------	-----------------------------	----------------------

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE James E. Edwards DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

WMOCC

*See Instructions on Reverse Side