X

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP-078931-B
Unit

## SUNDRY NOTICES AND REPORTS ON WELLS

	TION TO DRILL	SUBSE	QUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTEN	TION TO CHANGE PLANS	1 11	QUENT REPORT OF SHOOTING OR ACIDIZING	
	TION TO TEST WATER SHUT-OF	l li	QUENT REPORT OF ALTERING CASING	
	TION TO RE-DRILL OR REPAIR		QUENT REPORT OF REDRILLING OR REPAIR	
	TION TO SHOOT OR ACIDIZE	i H	QUENT REPORT OF ABANDONMENT	4
		4 11	EMENTARY WELL HISTORY	WEI
	ITION TO ABANDON WELL	1 1	TO LUCITY N	P
NUTICE OF INTER	IIIOM IO ADARDOR WELL		5 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
	(INDICATE ABOVE BY CH	ECK MARK NATURE OF	REPORT, NOTICE, OR OTHER DATA)	
			February 3.	19_54
6	allow		(F.)	
Well No	4 is located 9	20ft. from S Tu	ne and $\underline{GU}$ ft. from $\overline{W}$ line of sec.	
SWÈ	28	29N 131	(Meridian)	
(14 Sec. and	28 d Sec. No.) (Te	vp.) (Range)	(Meridian)	
		San Juan		
(Fi	eld)	(County or Subdivisio	on) (State or Territory)	
m 1		1 1 % 58	$834_{ m ft.}$ estimated $5826^{\circ}$ gro	und
State names of	f and expected depths to only ndicate muddling jobs, ce	objective sands; show menting points, and a	w sizes, weights, and lengths of proposed ca all other important proposed work)	sings;
1. <sup>-</sup> 2.	at appx. 1600'. Set pipe at to	of sand.	top of Pictured Cliffs sattools appx. 25' and compl	
1. 2. 3.	Drill with rot; at appx. 1600'. Set pipe at to; Drill into sanswell.	o of sand. I with eable	tools appx. 25' and compl	ete
1. 2. 3.	Drill with rot; at appx. 1600'. Set pipe at to; Drill into sanswell.	o of sand. I with eable		ete
1. 2. 3. I understa operations	Drill with rot; at appx. 1600; Set pipe at to; Drill into sand well.  and that this plan of work is may be commenced.	of sand. with cable	tools appx. 25' and compl	ete
1. 2. 3.	Drill with rot; at appx. 1600; Set pipe at to; Drill into sand well.  and that this plan of work is may be commenced.	of sand.  with cable  must receive approve	tools appx. 25' and compl	ete
1. 2. 3. I understa operations Company	Drill with rot; at appx. 1600'. Set pipe at to; Drill into sans well.  Indicate this plan of work is may be commenced.  Bay Patroleum	of sand.  with cable  must receive approve	tools appx. 25' and compl	ete
1. 2. 3. I understa operations Company	Drill with rote at appx. 1600' Set pipe at top Drill into sand well.  Indicate this plan of work a may be commenced.  Bay Petroleum.  1655 Grant. Si	of sand.  with cable  must receive approve	tools appx. 25' and compl	ete

and the first of the second of