Ta	State of New M	1exico	Form C-103
Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natural	Resources Department	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O.Box 2088			WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			3004507815 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE   6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name  Abrams Gas Com "E"
1. Type of Well: OIL GAS WELL OTHER Cathodic Protection			Atolania ada adin E
2. Name of Operator Attention: Amoco Production Company Lois Raeburn		8. Weli No.	
3. Address of Operator P.O. Box 800 Denver	Colorado 80201		9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter :	1790 Feet From The Sou	uth Line and 89	Po Feet From The East Line
Section 30	Township 29N		IMPM San Juan County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) N/A			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	DPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND		CASING TEST AND CEN	MENT JOB
OTHER: P & A Cat	hodic only	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
The Cathodic Protection well associated with the subject well will be plugged and abandoned per attached pro cedure.			
In addition, Amoco also request approval to construct a temporary 15' X 15' X 5' blow pit for return fluids. This pit well be reclaimed if utilized, upon completion of this procedure.			
			RECEIVED
			PEB 1 0 1995 12
			0[[L GON. D]V7. Din. 3
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Alla	Fackurn	BUSINESS A	NALYST DATE02-07-1995
TYPE OR PRINT NAME	Lois Raeburn Rm 1944		TELEPHONE NO.
(This space for State Use)			
APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH  TIT DEPUTY OIL & GAS INSPECTOR, DIST. #3  DATE FEB 2 ,2 1995  CONDITIONS OF APPROVAL, IF ANY:			

State of New Mexico

## **Ground Bed Abandonment Procedures**

Well Name: Abrahms Gas Com E 1

Location: I30-29N-10W

- 1. Weld 6" dia. spool with diverter line to pit
- 2. MIRU
- 3. Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to 281' (TD).
- 4. Pump adequate cement to partially fill hole (approx. 95 sx). Pull out work string.5. Top off hole with cement. Set flexible pipline marker as PxA marker.
- 6. RDMO

## **Ground Bed Specifications**

TD: 281'

Hole Dia.: 7" Casing Dia.: 7" Casing Length: 85'

1/6/95 mdr