## STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

August 27, 1985

Mr. Vincent F. Mirra
Union Texas Petroleum Corp.
P.O. Box 2120
Houston, TX 77252-2120

Re: Armenta #1 H-27-29N-10W

Dear Mr. Mirra:

In a letter to Mike Stogner (copy attached), you stated that you did not measure or report the gas volumes produced from the referenced well. This is in direct violation of Rule 403. Drilling gas used from a well is to be reported on form C-115 in the "other" column with the appropriate "code" explaination.

You are hereby directed to file amended reports for this well showing the appropriate volumes of gas production for the months that it produced gas for drilling.

Sincerely,

Frank T. Chavez District Supervisor

FTC/dj

xc: Mike Stogner

Well File Operator File



August 14, 1985

New Mexico Department of Energy and Minerals State Land Office Building P. O. Box 2088 Santa Fe, NM 87501

Attention: Mr. Mike Stogner

Armenta #1

Sect. 27, Township 29N,

Range 10W

NGPA Section: 108TPBU

Dear Mike:

Union Texas Petroleum Corporation, manager and operator Unicon Producing Company, filed for a temporary pressure buildup petition for the months of January, February March, 1985 and the reason for the shut in status for well was termed "drill gas" for January, 1985.

In checking with our district office in Farmington, I found that the well was disconnected from the meter and the production from that well was used by Southland Royalty as a drilling fluid to drill another well on the lease. actual production was not measured, however, we could probably estimate the production if this was needed.

I hope this explanation will suffice, however, if additional information is needed, please call me at (713) 866-2874.

Yours truly,

Vincent F. Mirra

Supervisor, Regulatory Affairs

VFM:da

A:VM-2.txt

OIL COM: DIV. DIST ?