

6	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

C-102 and C-103
 Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>PLUG AND ABANDON</u>		5. State Oil & Gas Lease No.
2. Name of Operator Douglas Kenaston % Bloomfield Oil Field Service		7. Unit Agreement Name
3. Address of Operator Box 1641, Bloomfield, New Mexico 87413		8. Farm or Lease Name Masden-Seib #2
4. Location of Well UNIT LETTER <u>A</u> <u>1000</u> FEET FROM THE <u>North</u> LINE AND <u>885</u> FEET FROM THE <u>East</u> LINE, SECTION <u>26</u> TOWNSHIP <u>22-N</u> RANGE <u>11-W</u> NMPM.		9. Well No. 2
15. Elevation (Show whether DF, RT, GR, etc.)		10. Field and Pool, or Wildcat
12. County San Juan		11. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-10-78 Rig up P & A rig go in hole with 2 3/8" tubing and 4 3/4 bit tag bottom at 403 feet. Rig up rotary tools. clean out to 469 feet. Drilling hard cement, mix and spot 39 sacks cement 2% calcium chloride W.O.C. over night. Tag cement next morning at 352 feet (hard) mix 40 sacks cement, swedge 8 5/8" back to 2" squeeze down 8 5/8" casing. shut well in W.O.C. cut 8 5/8 casing off 4 feet below ground level (cement very hard) clean up location.
 5-22-78 No 5 1/2 casing in this well.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. E. Bayler TITLE Manager DATE June 5, 1978
 APPROVED BY AR Hendrick TITLE SUPERVISOR DIST. #3 DATE JUN 5 1978
 CONDITIONS OF APPROVAL, IF ANY: