		/
/	1	Form C-103
NO. OF COPIES RECEIVED		Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Filective I-1-92
FILE		5a. Indicate Type of Lease
U.S.G.S.		State Fee.
OPERATOR '2		5. State Oil & Gas Lease No.
OPERATOR		
SUNDR	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
PAN AMERICAN PETROLEUM CORPORATION		Lefkovitz Gas Com "B"
3. Address of Operator 501 Airport Brive, Fa:	raington. New Mexico	9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
A	1150 FEET FROM THE NORTH LINE AND 790 FEET	Basin Dakota
UNIT LETTER		
THE LINE, SECTI	ION 25 TOWNSHIP 29-M RANGE 10-W N	MPM. (())
	15, Elevation (Show whether DF, RT, GR, etc.)	12. County
	\\\\\\ RDS 5581'	San Juan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	ALTERING CASING PLUG AND ABANDONMENT
OTHER		
vere taken: 1. On 5-10-67: 2. Pulled tubi: 3. Ran tubing:	bject well having indication of casing leaks, moved in workever unit and killed well with 2 mg and set bridge plug at 6205'. with packer to 4615'. Tested bridge plug with the content of	250 berrels treated water. Sh 3,000 psi for 1/2 hour
 4. On 5-11-67 and packer 5. Brilled bri 6. Ran tubing 	tested 4-1/2" casing with 3,500 psi for 1/2 hour QK. tested 4-1/2" casing with 3,500 psi for 1/2 h and tested casing with 1500 psi for 1/2 hour dge plug and cleaned out to PBD of 6450'. with packer and set at 6392'.	our OK. Pulled tuling
	1 and returned to production.	ree play gide
18. I hereby certify that the information G. W. Eaton, Jr.	n above is true and complete to the best of my knowledge and belief.	

PETROLEUM ENGINEER DIST: NO. 3

DATE August 2, 1967

AUG 3

1967

Orginal Signed By

As no indication of a casing lesk was found, no casing repairs were necessary.