

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

3004507921

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

Gail M. Jefferson

3. Address of Operator

P.O. Box 800

Denver

Colorado

80201

(303) 830-6157

8. Well No.

#1X

4. Well Location

Unit Letter

A

: 790

Feet From The

North

Line and

805

Feet From The

East

Line

Section

25

Township

29N

Range

10W

NMPM

San Juan

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company requests permission to plug and abandon the above referenced well per the attached procedures.

If you have any technical questions please contact Carollanne Wyett at (303) 830-5578 or Gail Jefferson for any administrative concerns.

RECEIVED  
AUG - 6 1996  
OIL CON. DIV.  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Gail M. Jefferson

TITLE

Sr. Admin. Staff Asst.

DATE

08-05-1996

TYPE OR PRINT NAME

Gail M. Jefferson

TELEPHONE NO. (303) 830-6157

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

AUG - 6 1996

CONDITIONS OF APPROVAL, IF ANY:

\* Notify OCD in time to witness

**Lefkovitz Gas Com 1X**  
**Orig. Comp. 4/57**  
**TD = 2025, PBTD 1988**  
**Page 2 of 2**

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
3. POOH with 1 1/4" tbg. RIH with 2/3/8" workstring and CIBP, set CIBP at 1875'.  
Test csg integrity to 500#. Spot 100' cement plug on top. ( 21 cuft cement)  
Pull up hole and spot 100' cement plugs as follows: 1730' 1630' Fruitland  
Coal, 720' to 620' Ojo Alamo and 250' to surface. (69 cuft cement)
4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
5. Contact FMC and ship surface equipment to yard or other location per instructions.
6. Turn over to John Schwartz for reclamation.
7. Rehabilitate location according to BLM or State requirements.