Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION** 

P.O.Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

WELL API NO.
30-045-07952
5. Indicate Type of Lease

e		45
STATE	FEE	Ł

PLUG AND ABANDONMENT

DISTRICT III

PERFORM REMEDIAL WORK

**TEMPORARILY ABANDON** 

**PULL OR ALTER CASING** 

work) SEE RULE 1103.

1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Prespentt Gas Com	,	
1. Type of Well: OIL GAS WELL 2	OTHER				
2. Name of Operator  Amoco Production Con	npany Attn: Ed Ha	dlock	8. Well No.	•	
3. Address of Operator P.O. Box 800 Denver CO 80201 (303) 830-4982		9. Pool name or Wildcat  Aztec - Pictured Cliffs			
4. Well Location Unit Letter O: 800		Line and 1700	Feet From The <u>East</u>	Line	
Section 21	Township 29N R	ange 10W N	MPM San Juan	County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5513' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	G 🗀	

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

x OTHER: Cathodic well abandonment OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

**CHANGE PLANS** 

The cathodic protection well associated with the subject well will be plugged and abandoned per the attached procedure.

DECEIVED

	OCT 0 8 1992 OIL CON. DII DIST. 3	
I hereby certify that the information above is true and complete to the best of  SIGNATURE	my knowledge and belief.  Admin Analyst  TITLE	DATE 10/6/92 TELEPHONE NO(303) 830-498
(This space for State Use)  APPROVED BY Since Si	DEPUTY OIL & GAS INSPECTOR, DIST. #3	SEP - 7 1993

## GROUND BED ABANDONMENT

WELL NAME: - Prospont # / LOCATION: Sec 21 Tup 29 RIC

- 1) Weld 6 " dia. spool with diverter line to pit
- 2) MIRU
- Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free, Wash hole to 10 &.
- 4) Pump \* sx of neat cement w/ 1/4 lb. sk. Flocele.
  Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

Ground Bed Specifications

TD 300 ft.

Hole Dia. \_\_\_\_\_inches.

Casing Dia. \_\_\_\_\_inches

Casing Length 70 ft.

\* Sacks of cement = (dia.) \* XT.D. X.00693 where dia. is in inches, TD is in feet

Note à A Nodre Depth : 280, 270, 260, 250, 240

JAB.GRA

water found @ 40 feet.