START TUCSDAY

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices	and Reports	on Wells	
,	and the second of the second o	API	# (assigned by OCD)
1. Type of Well GAS	ភ េខខ្លួ	5. VISA	Lease Number FEE State Oil&Gas Lease
2. Name of Operator Manana Gas, Inc.	OCT 20		Lease Name/Unit Name Hartman Well No.
3. Address & Phone No. of Operator 1002 Tramway lane NE Albuquerque, NM 87122 505-856-1084	OIL CON. DIGIL C		#1 Pool Name or Wildcat
4. Location of Well, Footage, Sec., T, R, P, Sec. 22, T-29-N, R-11-W, NMPM, Coun 990' FSL and 990' FEL		10.	Basin Dakota Elevation: 5436'
Type of Submission	Type of Act	ion	
X Notice of Intent X Abando	onment	Change	of Plans
Subsequent Report Pluggi	oletion Ing Back	New Con Non-Rou	struction tine Fracturing hut off ion to Injection
Final Abandonment Alteri Other	ing Casing	_ Convers	ion to Injection
13. Describe Proposed or Completed Operat	ions		
		NOTIFY AZ IN TIME TO	TEC OCD 24 hours
Manana Gas, Inc. proposes to plug	and abandon	this we	ll per a chul
the attached procedure. Cement CAPACITY of CAS			ll per 6 plum
#1 Plug 3950 ReT TO 6068 +	Excess		74
l'f Ret Not set @ 3950	ContAct	000	Office Aztec
SIGNATURE Ed Hartman		Se	eptember 4, 1998
(This space of sales by CRUCLE T. PERRIN Titoffully	OIL & GAS INSPECTO	R, DISTALL	OCT 2 0 1998

Note Hew attack

ED HARTMAN, PRES.

Mañana Gas, Inc. 2520 TRAMWAY TERRACE CT. N.E. ALBUQUERQUE, NEW MEXICO 87122

TELE: (505) 856-1084 FAX: (505) 856-1036


10/19/98

Bill Clark of A Plus Well Service worked this up and will do the actual plugging. His number is 325-2627.

Thanks

Ed Hartman

P.S.: I held up submitting this until I had approved AFE's from the working interest owners.



and the control of the state of the control of the



Hartman #1

Basin Dakota 990' FSL, 990' FEL / SE, Section 22, T-29-N, R-11-W San Juan Co., New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Manana safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and NU BOP. Test BOP.
- 2. PU 2" tubing. Round-trip 4-1/2" gauge ring to 3950' or as deep as possible. If tag is less than 3950', then spot cement plug as appropriate.
- 3. Plug #1 (Dakota and tubing stub, 3900' 3800'): Set 4-1/2" cement retainer at 3900'. Establish rate below retainer. Mix 62 sxs Class B cement, squeeze 50 sxs below retainer and spot leave 12 sxs above inside casing. Pressure test casing to 500#. If casing does not test, tag or spot subsequent plug as appropriate. POH with tubing.
- 4. Plug #2 (Mesaverde top, 3290' 3190'): Perforate 3 HSC squeeze holes at 3290'. Establish rate into squeeze holes if casing tested. Set 4-1/2" cement retainer at 3240'. Establish rate into squeeze holes. Mix 63 sxs Class B cement, squeeze 52 sxs cement outside casing and leave 11 sxs inside casing. PUH to 1690'.
- 5. Plug #3 (Pictured Cliffs and Fruitland tops, 1690' 1360'): Mix 28 sxs Class B cement and spot a balanced plug inside casing to cover Fruitland top. PUH to 640'.
- 6. Plug #4 (Kirtland and Ojo Alamo tops, 640* 304*): Mix 29 sxs Class B cement and spot a balanced plug inside casing to coach Ojo Alamo top. POH and LD tubing.
- 7. Plug #5 (Surface): Perforate 2 HSC squaeze holes at 50'. Establish circulation out bradenhead valve. Mix and pump approximately 20 sxs Class B cement down 4-1/2" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- 8. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Hartman #1

Current

Basin Dakota

SE, Section 22, T-29-N, R-11-W, San Juan County, NM

'Today's Date: 9/4/98 Spud: 3/13/60 Completed: 4/25/60 200 sxs (236cf) Squeezed into Elevation: 5436' (GL) bradenhead, displaced to 50'; Calculated Bottom of Cmt @ 694' (75%) 9-5/8" 33# Csg set @ 404' 300 sxs cement (Circulated to Surface) Ojo Alamo @ 354' 13-1/2" hole WORKOVER HISTORY May 96: 4-1/2" casing collapsed, 2-3/8" tbg stuck; Free point tbg apprx., 4000', back off tbg, Kirtland @ 667' attempt to fish, unable to recover any tubing. Top of Cmt @ 964' (Calc, 75%) Fruitland @ 1410' Pictured Cliffs @ 1640' DV tool @ 1795' Cmt w/340 cf Mesaverde @ 3240' 2-3/8" 4.7# tubing @ 6232' Freepoint and backed off at 4000' TOC @ 5174' (Calc, 75%) Gallup @ 5210' Dakota @ 6068' Dakota Perforations: 6072' - 6274' 4-1/2" 11.6# Casing set @ 6310' 8-3/4" Hole Cmt w/350 sxs + 50 sxs latex (465 cf)

TD 6310'

Hartman #1

Proposed P&A

Basin Dakota

SE, Section 22, T-29-N, R-11-W, San Juan County, NM

Plug #5 50' - Surface Cmt with 20 sxs Class B

Today's Date: 9/4/98

Spud: 3/13/60 Completed: 4/25/50 Elevation: 5436' (GL)

Ojo Alamo @ 354'

Kirtland @ 667'

Fruitland @ 1410

Pictured Cliffs @ 1640'

Mesaverde @ 3240'

Gallup @ 5210'

Dakota @ 6068'

Perforate @ 50'

200 sxs (236 cf) Squeezed into bradenhead, displaced to 50; Calculated Bottom of Cmt @ 694' (75%)

9-5/8" 33# Csg set @ 404' 300 sxs cement (Circulated to Surface)

Btm of Cmt @ 694' (Calc, 75%)

Plug #4 640' - 304' Cmt with 29 sxs Class B

Top of Cmt @ 964' (Calc, 75%)

> Plug #3 1690' - 1360' Cmt with 28 sxs Class B

DV tool @ 1795

Cmt w/340 cf

Plug #2 3290' - 3190' Cmt with 63 sxs Class B. 52 sxs outside casing

Cmt Retainer @ 3240'

and 11 sxs inside.

Perforate @ 3290'

Plug #1 3900' - 3800' Cmt with 62 sxs Class B,

Cmt Retainer @ 3900'

50 sxs below retainer and 12 sxs above.

2-3/8" 4.7# tubing @ 6232' Freepoint and backed off at 4000' TOC @ 5174' (Calc, 75%)

Dakota Perforations: 6072' - 6274'

4-1/2" 11.6# Casing set @ 6310' Cmt w/350 sxs + 50 sxs latex (465 cf)

8-3/4" Hole

13-1/2" nole